

CPUC

02/17/2012 OperationControlTicket vers. 1 JLD9 Original Page 1

Order 41620567 PATR/INSP 60067 DIXON-VACA #2+
Order type T180 EL TRANS EXPENSE RECURRING
Status REL PCNF DSEX NMAT PRC SETC
User Status UNSC
Start date 03/01/2012
End date 03/31/2012
FuncLocation ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Equipment 40577182 000/005 SINGLE WOOD POLE
MaintPlanGroup TLP ECES
MainWrkCenter SACTO Sacramento
Priority E E - Schd Compl Yr 0
MaintenancePlan
MaintPlanItem
Revision No.

Field

POSTED

Partner VLC5 JO
Address Conerly-Scott Veronica L.
Phone 916/760-3344 12345

Class ETLEQP Electric Transmission Line Equipment 002
ETL_FRAMINGCONFIG
LATITUDE 38.402685000000
LONGITUDE -121.911692000000
Class ETL_POLE 002
ETL_FRAMINGCONFIG
LATITUDE 38.402685000000
LONGITUDE -121.911692000000
Operation 0004 Transmission OH Detailed Inspection
Work center ET_TMAN1 ECES ELECTRIC TROUBLEMAN TRANSMISSION
Control key INDT CompConf No. 16309575
Operation key ETL03 Milestone
Work 12 MIN Activity type MO
Duration 30 DAY Number 1
EarlStartDate 03/01/2012 Start time 00:00:00
ateEndDate 03/31/2012 End time 00:00:00
Actual work 180 MIN Total buffer 0 MIN

NAME AND LAST OF QCR:	COOPER
SIGNATURE OF QCR:	Steve Cooper
# OF NEW TAGS GENERATED BY QCR:	24
SIGNATURE OF SUPERVISOR:	JTH 4/9/12
DATE	

COPY

Transmission Line Inspection Datasheet

Inspector Name : Cooper Date Inspection Completed : 3-28-12
 Miles Inspected : 16 # Structures Inspected : 57

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+
 Plan Group : TLP ET Poles
 Funct Loc : BTLL-6740-POLE-WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Oper Volt : 60 KV Line Miles : 16 M

Line Last Inspected : 41630193

DIXON-VACA #2 9/192 RPL CONNECTORS (Maintain Steel Structures)

02/09/2012 02/10/2012

MAT : BFZ Detailed Ground Inspections
 Work Center : ET-TMANL ELECTRIC TROUBLEMAN TRANSMISSION
 ABC : M Medium Impact ISO :

Struct Order: 571

Inspection Findings Data

Date Found	Structure #	Object	Damage	Priority	Comments	Est Hrs	Clearance Yes/No/Hot	Notification #
2-14-12	0/7	SW04	CH07	1year	RTN X ARM/BRACES			106000185
2-15-12	0/8	IHO10	MC02	3MON	BROKEN TIE WIRE			106000186
2-15-12	0/21	IHO10	MC02	3MON	BROKEN TIE WIRE			106000187
2-15-12	1/48	SW04	CH07	1year	RTN X ARM			106000349
2-21-12	2/57	SW04	CH07	1year	RTN X ARM - "Rollover"			106000240
2-26-12	3/88	SW01	MC23	3MON	Damaged Pole (6mons - 1yr) Replace			106015902
2-26-12	4/112	IHO10	MC10	1year	OVERSTRESSED POST ISSUE			106000244
3-6-12	7/166	SW01	CH10	6MONS	DAMAGED POLE - Stub (6mons)			106000247
3-6-12	8/179	CF10	CH10	1year	BOLTED CONNECTORS			106000248
3-6-12	13/288	SW04	CH07	2YR	RTN X ARM			106000300
3-8-12	14/300	IHO4	CH08	1 year	TRI PIN - REFLAME TO T-1			106000303
3-8-12	14/316	IHO4	CH08	1 year				106000391
3-8-12	15/318	IHO4	CH08	1 year				106000304
3-8-12	15/324	IHO4	CH08	1 year				106000306
3-8-12	15/327	AB-06	CH03	3YRN	(1) Auto Splice in D. (new) RTN POLE - Replace (REBURN to)			106000307
3-8-12	15/334	SW01	CH07	2 year	BROKEN BOND WIRE			106015866
3-8-12	16/351	SW07	MC02	1YRN				106000309
3-8-12	16/352	IHO4	CH08	1YEAR	TRI PIN - REFLAME TO T-1			106000395
3-8-12	18/385	SW07	MC02	1YRN	BROKEN BOND WIRE			106000309
3-8-12	19/387	SW07	MC02	1YRN				106000349

Supervisor's Initials: _____

Transmission Line Inspection Datasheet

Inspector Name : Cooper Date Inspection Completed : 3-29-12
Miles Inspected : 16 # Structures Inspected : 571

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+
 Plan Group : TLP ET Poles
 Funct Loc : EST. 6740.ROLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Oper Volt : 60 KV Line Miles : 16 M

MAT : BFZ Detailed Ground Inspections
Work Center : ET_TWANL ELECTRIC TROUBLEMAN TRANSMISSION
ABC : M Medium Impact ISO :
Struct Order: 571

Line Last Inspected : 41630193 DIXON-VACA #2 9/192 RPL CONNECTORS (Maintain Steel Structures)

03/09/2012 03/10/2012

Inspection Findings Data

Date Found	Structure #	Object	Damage	Priority	Comments	Est Hrs	Clearance Yes/No/Hot	Notification #
3-5-12	19/410	SWD#	LHD7	1 year	R/TN X AEN BRCE, minor Arm ret.	106000398		
3-11-12	A5/106	IHO3	MC2	1 year	BROKEN INSUL'S - C-PIN IN-Phase	106000344		
3-23-12	A7/173	MA10	MC15	1 year	XING MARKER MISSING	106000347		
JJ	A10/225	CP14	CH10	2 year	(2) Auto Splices IN Conductor AT Pole.	106000346		
2-14-12	O/S	IHO5	ELO5	2 year	FLASHED D.E. INSULATOR	106000384		

Supervisor's Initials:

三

Date Reviewed:

49/2

Transmission Line Inspection Datasheet

Inspector Name : Cooper **Date Inspection Completed :** 3-28-12
Miles Inspected : 16 **# Structures Inspected :** 571

Order	:	41620567	PATR/INSP	60067	DIXON-VACA #2+
Plan Group	:	TLP	ET	POLES	
Funct	Loc	ETL 6740 POLE, WOOD	60067	DIXON-VACA #2+	-WOOD POLE
Oper	Volt	60 KV	Line Miles	16 M	

MAT : BFZ Detailed Ground Inspections
Work Center : ET_TMANL ELECTRIC TROUBLEMAN TRANSMISSION
ABC : M Medium Impact ISO :
Struct Order : 571

Line Last Inspected : 41630193 **DIXON-VACA #2 9/192 RPL CONNECTORS** (Maintain Steel Structures)

02/09/2012 02/10/2012

Inspection Findings Data

Completed Minor Work

Date Found	structure #	Object	Damage	Priority	Comments	Est Hrs	Clearance Yes/No	Notification #
3-15-12	1/51				Dug out Buried Anchor Rod			
	4/75				↓ ↓ ↓ ↓ ↓			
3-20-12	7/170							
3-5-12	11/237							
3-8-12	14/309				CLEANED UP POLES / INSUL DEBRIS			
	16/350				DUG OUT BURIED ANCHOR ROD			
3-6-12	17/363				↓ ↓ ↓ ↓ ↓			
	17/376							
3-5-12	18/386				INSTALLED V'S STRAPS			
	18/389				CLEANED UP POLE / INSUL DEBRIS			
	19/402				INSTALLED GUY MARKER			
3-23-12	A7/157				RE-ATTACHED FIBEROPTIC TO POLE			
	A10/216				TRIMMED OUT TREE			

Inspected by: COOPER

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Date Inspected: 2-14-12

Structures Inspected: From 0/1 To 1/44

Date Inspected: 3-15-12

Structures Inspected: From 1/45 To 3/78

Date Inspected: 3-21-12

Structures Inspected: From 3/79 To 4/112

Date Inspected: 3-28-12

Structures Inspected: From 4/113 To 5/130

Date Inspected: 3-20-12

Structures Inspected: From 5/131 To 6/146

Date Inspected: 3-26-12

Structures Inspected: From 6/147 To 9/191

Date Inspected: 3-20-12

Structures Inspected: From 9/192 To 10/222

Date Inspected: 3-9-12

Structures Inspected: From 10/223 To 11/234

Date Inspected: 3-5-12

Structures Inspected: From 11/235 To 12/274

Date Inspected: 3-6-12

Structures Inspected: From 12/275 To 13/290

Date Inspected: 3-8-12

Structures Inspected: From 13/291 To 17/362

Notes: _____

Inspected by: COOPER

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Date Inspected: 3-6-12

Structures Inspected: From 17/363 To 18/378

Date Inspected: 3-5-12

Structures Inspected: From 18/379 To 19/410

Date Inspected: 3-4-12

Structures Inspected: From 19/411 To A3/79

Date Inspected: 3-19-12

Structures Inspected: From A3/080 To A5/119

Date Inspected: 3-28-12

Structures Inspected: From A5/120 To A7/151

Date Inspected: 3-23-12

Structures Inspected: From A7/152 To A9/199

Date Inspected: 2-24-12

Structures Inspected: From A9/200 To A10/215

Date Inspected: 3-23-12

Structures Inspected: From A10/216 To B7/179

Date Inspected:

Structures Inspected: From _____ To _____

Date Inspected:

Structures Inspected: From _____ To _____

Date Inspected:

Structures Inspected: From _____ To _____

Notes:

Transmission Line Object List

Inspector Name : COOPER

Date Inspected : 2-14-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
000/001 SINGLE WOOD POLE 40589508 TRI PIN ARM DEAD END MEDIUM EQP(AERIAL LIFT;LINE TR	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015951 ENTER AT S.E. CORNER OF VACA DIXON SUB PARKING LOT.
38.401192000000 -121.9180730000		
000/002 SINGLE WOOD POLE 40669889 FLAT PIN ARM MEDIUM EQP(AERIAL LIFT;LINE TR	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015950 ENTER AT S.E. CORNER OF PARKING LOT AT VACA DIXON SUB.
38.401717000000 -121.9174570000		
000/005 SINGLE WOOD POLE 40577182 TRI PIN ARM DEAD END	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Guystab Leaning, out of line Notes: '02 Survey: C015945
38.402685000000 -121.9116920000		
000/006 SINGLE WOOD POLE 40767461 TRI PIN ARM	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015944
38.402706000000 -121.9109430000		
000/007 SINGLE WOOD POLE 40814251 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: * Arm! Beses R#N Notes: '02 Survey: C015943 MONITOR XARM
38.402698000000 -121.9102010000		
000/008 SINGLE WOOD POLE 40823432 TRI PIN ARM	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: hoose Tie wire - Broken Notes: '02 Survey: C015942
38.402675000000 -121.9094590000		
000/009 SINGLE WOOD POLE 40865907 TRI PIN ARM	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015941
38.402683000000 -121.9087320000		
000/010 SINGLE WOOD POLE 40874353 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015940
38.402694000000 -121.9079880000		

* No 3, 4 - guys on towers

Transmission Line Object List

Page 2

Inspector Name : Cooper
Date Inspected : 2-14-02

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
000/011 SINGLE WOOD POLE 40612558 ANGLE 0-30 DEGREES 38.402705000000 -121.9073330000	<input type="checkbox"/> completed/no problems. <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>INSTALL Shunts over Gray Autowire</i> Notes: '02 Survey: C015939
000/012 SINGLE WOOD POLE 40599351 TRI PIN ARM DEAD END 38.402544000000 -121.9068820000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015938
000/013 SINGLE WOOD POLE 40665893 ANGLE 0-30 DEGREES 38.402276000000 -121.9060150000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015937
000/014 SINGLE WOOD POLE 40665457 TRI POST 38.402227000000 -121.9052540000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015936
000/015 SINGLE WOOD POLE 40756174 TRI POST 38.402240000000 -121.9046250000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015935
000/016 SINGLE WOOD POLE 40767463 TRI POST 38.402273000000 -121.9039150000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015934
000/017 SINGLE WOOD POLE 40825135 ANGLE 0-30 DEGREES 38.402268000000 -121.9032460000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015933
000/018 SINGLE WOOD POLE 40599377 TRI PIN ARM DEAD END 38.402510000000 -121.9021540000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015932

Transmission Line Object List

Page 3

Inspector Name : Cooper
Date Inspected : 2-14-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
000/019 SINGLE WOOD POLE 40695347 ANGLE 0-30 DEGREES 38.402654000000 -121.9017120000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015921	Total # of Attachments: <i>Pole has "C" Truss</i>
000/020 SINGLE WOOD POLE 40654066 TRI PIN ARM 38.402670000000 -121.9009680000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015920	Total # of Attachments:
000/021 SINGLE WOOD POLE 40756176 TRI PIN ARM 38.402691000000 -121.9002490000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015929	Total # of Attachments: <i>3 broke tie wire X arm R/TN</i>
000/022 SINGLE WOOD POLE 40767465 TRI PIN ARM 38.402673000000 -121.8994900000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015928	Total # of Attachments:
000/023 SINGLE WOOD POLE 40814253 3 HORIZONTAL POST DELTA 38.402662000000 -121.8987650000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015927	Total # of Attachments:
000/024 SINGLE WOOD POLE 40813427 TRI PIN ARM 38.402638000000 -121.8979860000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015926	Total # of Attachments:
000/025 SINGLE WOOD POLE 40875450 ANGLE 0-30 DEGREES 38.402655000000 -121.8972790000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015925	Total # of Attachments:
000/026 SINGLE WOOD POLE 40865367 ANGLE 0-30 DEGREES 38.402341000000 -121.8965290000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015924	Total # of Attachments:

Transmission Line Object List

Page 4

Inspector Name : COOPER
Date Inspected : 2-14-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE Medium Impact
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
001/027 SINGLE WOOD POLE 40612543 TRI PIN ARM 38.402348000000 -121.8958580000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015923
001/028 SINGLE WOOD POLE 40599366 TRI POST 38.402309000000 -121.8950090000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015922
001/029 SINGLE WOOD POLE 40669898 TRI PIN ARM HEAVY EQP (CRANES, TRACTOR) 38.402383000000 -121.8942000000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015921 ON WEBER EAST OF LEWIS
001/030 SINGLE WOOD POLE 40654068 TRI PIN ARM 38.402364000000 -121.8935630000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015920
001/031 SINGLE WOOD POLE 40756178 TRI POST 38.402400000000 -121.8927870000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015919
001/032 SINGLE WOOD POLE 40767471 TRI PIN ARM 38.402349000000 -121.8919940000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015918
001/033 SINGLE WOOD POLE 40814255 TRI PIN ARM 38.402354000000 -121.8912560000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015917
001/034 SINGLE WOOD POLE 40823438 TRI PIN ARM 38.402338000000 -121.8904800000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015916

Transmission Line Objec. List

Page 5

Inspector Name : COOPER

Date Inspected : 2-14-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
001/035 SINGLE WOOD POLE 40875440 TRI PIN ARM 38.402356000000 -121.8897080000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015915
001/036 SINGLE WOOD POLE 40874359 TRIANGLE POST 70 38.402343000000 -121.8889600000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015914
001/037 SINGLE WOOD POLE 40596041 TRI PIN ARM 38.402320000000 -121.8881800000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015913
001/038 SINGLE WOOD POLE 40599387 TRI PIN ARM 38.402316000000 -121.8874510000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015912
001/039 SINGLE WOOD POLE 40669902 TRI PIN ARM 38.402324000000 -121.8867190000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015911
001/040 SINGLE WOOD POLE 40599354 TRI PIN ARM 38.402315000000 -121.8860170000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015910
001/041 SINGLE WOOD POLE 40695377 TRI PIN ARM 38.402331000000 -121.8853150000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015909
001/042 SINGLE WOOD POLE 40665461 TRI PIN ARM 38.402329000000 -121.8846230000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015908

Pole has "C" Truss

Transmission Line Objec. List

Page 6

Inspector Name : COOPER
Date Inspected : 3-15-12

Funct Loc : ETL.6740 POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE Medium Impact
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
		Attachment Type/Owner Listed
Equip #	Notes	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
001/043 SINGLE WOOD POLE 40755180 TRI PIN ARM 38.402330000000 -121.8839390000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015907
001/044 SINGLE WOOD POLE 40755087 TRI PIN ARM 38.402322000000 -121.8832730000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015906
001/045 SINGLE WOOD POLE 40825123 TRI PIN ARM 38.402303000000 -121.8825830000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015905
001/046 SINGLE WOOD POLE 40813429 TRI PIN ARM 38.402321000000 -121.8819030000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015904
001/047 SINGLE WOOD POLE 40875423 TRI PIN ARM 38.402322000000 -121.8812350000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015903
001/048 SINGLE WOOD POLE 40865369 TRI PIN ARM 38.402305000000 -121.8805600000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015902 <i>Ren X arm - 1 year.</i>
001/049 SINGLE WOOD POLE 40612546 TRI PIN ARM 38.402326000000 -121.8793860000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015901
001/050 SINGLE WOOD POLE 40589509 TRI PIN ARM 38.402326000000 -121.8787650000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 <i>Pole Has "C" Truss</i>

2-14

3-15-

Transmission Line Object List

Page 7

Inspector Name : COOPER
Date Inspected : 3-15-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
001/051 SINGLE WOOD POLE 40669906 DOUBLE VERTICAL 38.402306000000 -121.8780470000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015899	Total # of Attachments:
001/052 SINGLE WOOD POLE 40665464 TRI PIN ARM 38.401674000000 -121.8780630000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015898	Total # of Attachments:
002/053 SINGLE WOOD POLE 40756182 TRI PIN ARM DEAD END 38.401170000000 -121.8780530000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015897	Total # of Attachments:
002/054 SINGLE WOOD POLE 40767473 TRI PIN ARM 38.400535000000 -121.8780380000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015896	Total # of Attachments:
002/055 SINGLE WOOD POLE 40825121 TRI PIN ARM 38.399955000000 -121.8780060000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015895	Total # of Attachments:
002/056 SINGLE WOOD POLE 40823456 TRI PIN ARM 38.399349000000 -121.8780250000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015894	Xarm REN - 14n
002/057 SINGLE WOOD POLE 40865909 TRI PIN ARM 38.398776000000 -121.8780310000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015893	Xarm REN { Ruler
002/058 SINGLE WOOD POLE 40874357 TRI PIN ARM 38.398172000000 -121.8779750000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015892	Total # of Attachments:

Transmission Line Object List

Page 8

Inspector Name : COOPER

Date Inspected : 3-15-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result [] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol	Attachments #
		Attachment Type/Owner Listed
002/059 SINGLE WOOD POLE 40596044 TRI PIN ARM 38.397558000000 -121.8779520000	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015891
002/060 SINGLE WOOD POLE 40599388 TRI PIN ARM 38.396947000000 -121.8779490000	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015890
002/061 SINGLE WOOD POLE 40681685 TRI PIN ARM 38.396360000000 -121.8779910000	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015899
002/062 SINGLE WOOD POLE 40665460 TRI PIN ARM 38.395740000000 -121.8780070000	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015888
002/063 SINGLE WOOD POLE 40756184 TRI PIN 38.394938000000 -121.8779690000	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015887
002/064 SINGLE WOOD POLE 40767469 TRI PIN ARM 38.394490000000 -121.8779270000	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015886
002/065 SINGLE WOOD POLE 40814259 TRI PIN ARM 38.393902000000 -121.8779050000	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015885
002/066 SINGLE WOOD POLE 40823436 TRI PIN ARM 38.393267000000 -121.8779350000	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015884

Transmission Line Object List

Page 9

Inspector Name : Cooper
Date Inspected : 3-15-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
		Attachment Type/Owner Listed
Equip #	Notes	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
002/067 SINGLE WOOD POLE 40589511 TRI PIN ARM 38.392698000000 -121.8779520000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015883
002/068 SINGLE WOOD POLE 40695352 TRI PIN ARM 38.392109000000 -121.8779200000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015882
002/069 SINGLE WOOD POLE 40659336 TRI PIN ARM 38.391478000000 -121.8778670000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015881
002/070 SINGLE WOOD POLE 40756186 TRI PIN ARM 38.390980000000 -121.8779100000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015880
002/071 SINGLE WOOD POLE 40767467 TRI PIN ARM 38.390290000000 -121.8778930000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015879
002/072 SINGLE WOOD POLE 40814257 TRI PIN ARM 38.389789000000 -121.8779050000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015878
002/073 SINGLE WOOD POLE 40823434 TRI PIN 38.389064000000 -121.8778630000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015877
002/074 SINGLE WOOD POLE 40865911 TRI PIN ARM 38.388473000000 -121.8778160000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015876

Transmission Line Object List

Page 10

Inspector Name : COOPER
Date Inspected : 3-21-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result [] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol	Attachments # Attachment Type/Owner Listed	B-159
002/075 SINGLE WOOD POLE 40874355 TRIANGLE POST 70 38.387834000000 -121.8778410000	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol	Total # of Attachments: <i>Dug out required Anchor Rod</i>	Notes: '02 Survey: C015875
002/076 SINGLE WOOD POLE 40596047 TRIANGLE POST 70 38.387157000000 -121.8777190000	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol	Total # of Attachments: 	Notes: '02 Survey: C015874
002/077 SINGLE WOOD POLE SW 69 40599352 FIELD SWITCH STRUCTURE MEDIUM EQP(AERIAL LIFT,LINE TR 38.386742000000 -121.8777170000	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol	Total # of Attachments: <i>Cane Veg around SW - Blackberries</i>	Notes:
003/078 SINGLE WOOD POLE 41122407 LINE AND BUCK 38.385820000000 -121.8776470000	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol	Total # of Attachments: <i>Vaca Sct</i>	Notes: '02 Survey: C015872 TO TRAVIS JCT Equip. not in GAD
003/079 SINGLE WOOD POLE SW 47 40665497 FIELD SWITCH STRUCTURE 38.386027000000 -121.8774870000	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol	Total # of Attachments: <i>T-(v/c)</i>	Notes:
003/080 SINGLE WOOD POLE 40677815 TRIANGLE POST 70 38.386587000000 -121.8769770000	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol	Total # of Attachments: <i>T-(v/c)</i>	Notes: '02 Survey: C015870
003/081 SINGLE WOOD POLE 40599409 TRIANGLE POST 70 38.387256000000 -121.8764050000	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol	Total # of Attachments: <i>T-(v/c)</i>	Notes: '02 Survey: C015869
003/082 SINGLE WOOD POLE 40612595 TRIANGLE POST 70 38.387900000000 -121.8758960000	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol	Total # of Attachments: <i>T-(v/c)</i>	Notes: '02 Survey: C015868

Transmission Line Objec. List

Page 11

Inspector Name : COOPER
Date Inspected : 3-21-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
003/083 SINGLE WOOD POLE 40868361 TRI POST TH(c) 38.388418000000 -121.8753650000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015867	Total # of Attachments: <i>Old Party Cabin Pole</i>
003/084 SINGLE WOOD POLE 40869028 TRI POST TH(c) 38.388989000000 -121.8748500000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015866	Total # of Attachments: <i>Pole Hammer tests ok: fully press fit pole & bag of rock laying onsite</i>
003/085 SINGLE WOOD POLE 40823476 TRI POST TH(c) 38.389573000000 -121.8743280000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015865	Total # of Attachments: <i>Found Stub Installed, work completed</i>
003/086 SINGLE WOOD POLE 40817776 TRI POST TH(c) 38.390189000000 -121.8737840000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015864	Total # of Attachments: <i>Pole Replace <found "C" truss installed - ok</i>
003/087 SINGLE WOOD POLE 41122284 TRI POST TH(c) 38.390793000000 -121.8732710000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015863	Total # of Attachments: <i>Pole Damaged by Ag Equip. - Replace</i>
003/088 SINGLE WOOD POLE 40759684 TRI POST 38.391434000000 -121.8727050000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015862	Total # of Attachments: 1 DIST-0310456 1
003/089 SINGLE WOOD POLE 40759928 TRI POST TH(c) 8.392079000000 121.8721190000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015861	Total # of Attachments: 1 DIST-0310456 1
003/090 SINGLE WOOD POLE 0657552 HORIZONTAL POST DELTA SHORT 8.392586000000 121.8716510000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015860	Total # of Attachments:

Transmission Line Objec. List

Page 12

Inspector Name : Cooper

Date Inspected : 3-21-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE Medium Impact
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
003/091 SINGLE WOOD POLE 40695473 TRI POST SHPD(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015859
38.393157000000 -121.8711520000		
003/092 SINGLE WOOD POLE 40592639 TRI POST TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015858
38.393771000000 -121.8705860000		" RATTIG OLD CEDAR "
003/093 SINGLE WOOD POLE 40868360 TRI POST TH(c)	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015857
38.394368000000 -121.8700810000		
003/094 SINGLE WOOD POLE 40875454 TRI POST TH(c)	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015856 TECH ID=004/086
38.394979000000 -121.8695240000		
003/095 SINGLE WOOD POLE 40823474 TRI POST TH(c)	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015855 Replace Insulator - No changes
38.395590000000 -121.8690170000		
003/096 SINGLE WOOD POLE 40817774 TRI POST TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015854 MONITOR POSSIBLE N/G POLE - looks RATTIG, Hammer test OK.
38.396103000000 -121.8685070000		
003/097 SINGLE WOOD POLE 40767504 TRI POST TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015853
38.396727000000 -121.8680020000		
004/098 SINGLE WOOD POLE 40768162 TRI POST TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015852
38.397317000000 -121.8674250000		

Transmission Line Objec. List

Page 13

Inspector Name : COOPER

Date Inspected : 3-21-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
004/099 SINGLE WOOD POLE 40665503 TRI POST TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015851
38.397943000000 -121.8669130000		
004/100 SINGLE WOOD POLE 40677810 TRI POST TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015850
38.398583000000 -121.8663550000		
004/101 SINGLE WOOD POLE 40599390 TRI POST TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015849
38.399144000000 -121.8658420000		
004/102 SINGLE WOOD POLE 40612592 TRI POST TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015848
38.399693000000 -121.8653440000		
004/103 SINGLE WOOD POLE 40874389 TRI POST T-1(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015847
38.400273000000 -121.8648230000		
004/104 SINGLE WOOD POLE 40869026 TRI POST TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015846
38.400898000000 -121.8642620000		Pole HAS "C" fruss
004/105 SINGLE WOOD POLE 40823478 TRI PIN ARM DEAD END ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015845
38.401483000000 -121.8637430000		Pole HAS Wood Scrub
004/106 SINGLE WOOD POLE 40817772 TRI POST TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015844
38.402129000000 -121.8631480000		

Transmission Line Object List

Page 14

Inspector Name : COOPER

Date Inspected : 3-21-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
		Attachment Type/Owner Listed
Equip #	Notes	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
004/107 SINGLE WOOD POLE 40759681 T-1(C) LINE AND BUCK <i>To Under slant</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015843 BATAVIA TAP
38.402641000000 -121.8626800000		
004/108 SINGLE WOOD POLE 40768142 TRI POST T-1(N/C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015842
38.403276000000 -121.8621610000		
004/109 SINGLE WOOD POLE 40665525 TRI POST T-1(N/C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015841
38.403797000000 -121.8616830000		
004/110 SINGLE WOOD POLE 40677806 TRI POST T-1(N/C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015840
38.404366000000 -121.8611870000		
004/111 SINGLE WOOD POLE 40586218 TRI POST T-1(N/C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015839
38.405050000000 -121.8606000000		
004/112 SINGLE WOOD POLE 40874385 TRI POST T-1(N/C)	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>N/C Post Insul (top &) over stressed</i> Notes: '02 Survey: C015838
38.405541000000 -121.8601070000		
004/113 SINGLE WOOD POLE 40875456 TRI POST	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015837 REFRAME POLE 8/14/2001 - COMPLETED NOTIFICATION ON 12/22/2003 - ENTERED INTO EQUIPMENT RECORE ON 12/22/2003
38.405886000000 -121.8596290000		
004/114 SINGLE WOOD POLE 40816645 TRI POST	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015836
38.406331000000 -121.8589510000		

3-21-12

3-28-13

Transmission Line Objec. List

Page 15

Inspector Name : Cooper

Date Inspected : 3-28-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
004/115 SINGLE WOOD POLE 40817770 ANGLE 30-80 DEGREES 38.406716000000 -121.8583370000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015835
004/116 SINGLE WOOD POLE 40767502 TRI POST 38.407188000000 -121.8581570000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015834
004/117 SINGLE WOOD POLE 40768148 TRI POST DEAD END 60 38.407955000000 -121.8579830000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015833
004/118 SINGLE WOOD POLE 40665522 TRI POST 38.408251000000 -121.8577470000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015832
004/119 SINGLE WOOD POLE 40695452 TRI POST 38.408892000000 -121.8572560000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015831
005/120 SINGLE WOOD POLE 40592638 TRI POST 38.409442000000 -121.8567120000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015830
005/121 SINGLE WOOD POLE 40590230 TRI POST 38.410059000000 -121.8562630000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015829
005/122 SINGLE WOOD POLE 40874391 TRI POST 38.410641000000 -121.8556390000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015828

Transmission Line Object List

Page 16

Inspector Name : Cooper

Date Inspected : 3-28-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
005/123 SINGLE WOOD POLE 40875473 TRI POST 38.412100000000 -121.8550600000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015827	Total # of Attachments:
005/124 SINGLE WOOD POLE 40823480 TRI POST 38.411822000000 -121.8545630000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015826	Total # of Attachments:
005/125 SINGLE WOOD POLE 40817768 TRI POST 38.412610000000 -121.8539900000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015825	Total # of Attachments:
005/126 SINGLE WOOD POLE 40767506 TRI POST 38.413159000000 -121.8534100000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015824	Total # of Attachments:
005/127 SINGLE WOOD POLE 40768146 TRI POST 38.413878000000 -121.8527930000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015823	Total # of Attachments:
005/128 SINGLE WOOD POLE 40657550 TRI POST 38.414616000000 -121.8521090000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015822	Total # of Attachments:
005/129 SINGLE WOOD POLE 40677802 TRI POST 38.415270000000 -121.8515290000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015821	Total # of Attachments:
005/130 SINGLE WOOD POLE 40599391 TRI POST 38.415780000000 -121.8510410000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015820	Total # of Attachments:

Transmission Line Object List

Page 17

Inspector Name : COOPER
 Date Inspected : 3-20-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
 Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
005/131 SINGLE WOOD POLE 40665505 TRI POST	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015819
38.416575000000 -121.8503420000		
005/132 SINGLE WOOD POLE 40677798 TRI POST	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015818
38.416909000000 -121.8500420000		
005/133 SINGLE WOOD POLE 40599393 TRI POST	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015817
38.417182000000 -121.8498040000		
005/134 SINGLE WOOD POLE 40601256 ANGLE 30-80 DEGREES	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015816
38.417941000000 -121.8491410000		
005/135 SINGLE WOOD POLE 40874393 TRI POST	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015815
38.418700000000 -121.8484890000		
005/136 SINGLE WOOD POLE 40869024 TRI POST	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015814
38.419407000000 -121.8478170000		
005/137 SINGLE WOOD POLE .0823492 TRI POST	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015813
8.420127000000 121.8471620000		
005/138 SINGLE WOOD POLE 0817766 RI POST	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015812
3.420747000000 121.8466670000		

Transmission Line Object List

Page 18

Inspector Name : Cooper

Date Inspected : 3-20-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
		Attachment Type/Owner Listed
Notes		
006/139 SINGLE WOOD POLE 40759679 TRI POST T-1(c) MEDIUM EQP(AERIAL LIFT;LINE TR	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
38.421342000000 -121.8461250000	Notes: '02 Survey: C015811	
006/140 SINGLE WOOD POLE 40759926 TRI POST T-1(c) 38.421898000000 -121.8456040000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
Notes: '02 Survey: C015810		
006/141 SINGLE WOOD POLE 40665520 TRI POST T-1(c) 38.422499000000 -121.8450730000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
Notes: '02 Survey: C015809		
006/142 SINGLE WOOD POLE 40677795 TRI POST T-1(c) 38.423095000000 -121.8445180000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
Notes: '02 Survey: C015808		
006/143 SINGLE WOOD POLE 40592636 TRI POST T-1(c) 38.423746000000 -121.8439690000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
Notes: '02 Survey: C015807		
006/144 SINGLE WOOD POLE 40612583 TRI POST T-1(c) 38.424281000000 -121.8434960000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
Notes: '02 Survey: C015806		
006/145 SINGLE WOOD POLE 40874395 TRI POST T-1(c) 38.424856000000 -121.8430110000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
Notes: '02 Survey: C015805		
006/146 SINGLE WOOD POLE 40869021 TRI POST SV 38.425220000000 -121.8426630000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
Notes: '02 Survey: C015804		

Transmission Line Objec. List

Page 19

Inspector Name : COOPER

Date Inspected : 3-26-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
006/147 SINGLE WOOD POLE 40823482 TRI POST SV	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015803
38.425859000000 -121.8427540000		
006/148 SINGLE WOOD POLE 40825165 TRI POST T-1(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015802
38.426277000000 -121.8423740000		
006/149 SINGLE WOOD POLE 40767508 TRI POST T-1(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015801
38.426892000000 -121.8418250000		
006/150 SINGLE WOOD POLE 40759924 ANGLE 30-80 DEGREES T-1(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015800
38.427153000000 -121.8415540000		
006/151 SINGLE WOOD POLE 40665527 TRI POST T-1(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015799
38.428009000000 -121.8408650000		
006/152 SINGLE WOOD POLE 40677791 TRI POST T-1(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015798
38.428668000000 -121.8402470000		
006/153 SINGLE WOOD POLE 40599394 TRI POST T-1(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015797
38.429277000000 -121.8397300000		
006/154 SINGLE WOOD POLE 40874407 TRI POST T-1(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015796
38.429889000000 -121.8392060000		

Transmission Line Object List

Page 20

Inspector Name : COOPER
Date Inspected : 3-26-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Medium Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
006/155 SINGLE WOOD POLE 40875459 TRI POST T-1(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015795
006/156 SINGLE WOOD POLE 40816643 TRI POST T-1(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015794
006/157 SINGLE WOOD POLE 40825153 TRI POST 3XPD(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015793
007/158 SINGLE WOOD POLE 40759677 TRI POST T-1(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015792
007/159 SINGLE WOOD POLE 40759922 TRI POST T-1(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015791
007/160 SINGLE WOOD POLE 40657549 TRI POST T-1(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015790
007/161 SINGLE WOOD POLE 40695456 TRI POST T-1(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015789
007/162 SINGLE WOOD POLE 40592635 TRI POST T-1(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015788
8.434683000000 121.8349950000		

Transmission Line Object List

Page 21

Inspector Name : Cooper

Date Inspected : 3-26-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
007/163 SINGLE WOOD POLE 40612586 TRI POST <u>T-1 (n/c)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015787
38.435285000000 -121.8344840000		
007/164 SINGLE WOOD POLE 40868357 TRI POST <u>T-1(c)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015786
38.435830000000 -121.8339210000		
007/165 SINGLE WOOD POLE 40875461 TRI POST <u>T-1(c)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015785
38.436417000000 -121.8333890000		
007/166 SINGLE WOOD POLE 40823484 TRI POST <u>T-1(c)</u>	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015784 <i>Pole cut at G/L - Stub</i> <i>6 mons.</i>
38.437001000000 -121.8328370000		
007/167 SINGLE WOOD POLE 40825163 TRI POST <u>T-1(c)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015783
38.437644000000 -121.8323600000		
007/168 SINGLE WOOD POLE 40767510 TRI POST <u>T-1(c)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015782
38.438275000000 -121.8318580000		
007/169 SINGLE WOOD POLE 40768151 TRI POST <u>T-1(c)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015781
38.438829000000 -121.8312900000		
007/170 SINGLE WOOD POLE 0665523 TRI POST <u>T-1(c)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015780
38.439466000000 -121.8307890000		

Transmission Line Objec. List

Page 22

Inspector Name : COOPER
Date Inspected : 3-26-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE Medium Impact
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
007/171 SINGLE WOOD POLE 40677787 TRI POST T-1(c) 38.440248000000 -121.8300320000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015779
007/172 SINGLE WOOD POLE 40599396 TRI POST T-1(c) 38.441010000000 -121.8293300000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015778
007/173 SINGLE WOOD POLE 40869019 TRI POST T-1(e) 38.441857000000 -121.8286020000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 2 CABL-UNKNOWN 1; DIST-0310456 1 Notes: '02 Survey: C015777
007/174 SINGLE WOOD POLE 40816641 TRI POST T-1(c) 38.442391000000 -121.8280890000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015776
007/175 SINGLE WOOD POLE 40817764 TRI POST T-1(c) 38.442980000000 -121.8275790000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015775
007/176 SINGLE WOOD POLE 40759675 FIELD SWITCH STRUCTURE 38.443565000000 -121.8270230000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>* Dig out Buring Dist Anchored</i> Notes:
007/177 SINGLE WOOD POLE 40768160 TRI POST T-1(s) 38.444259000000 -121.8263940000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015773
007/178 SINGLE WOOD POLE SW 29 41122282 DIXON SUB 38.444871000000 -121.8259300000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:

Transmission Line Object List

Page 23

Inspector Name : Couper

Date Inspected : 3-26-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
008/179 TUBULAR STEEL POLE 40665506 LATTICE DOUBLE VERTICAL	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: X BOLTED CONNS <small>Notes: '02 Survey: C015404 DELETE DUPLICATE ASSET STRUCTURE IS FIELD SWITCH STRUCTURE No need for separate pole record</small>
38.445041000000 -121.8258320000		
008/180 CERAMIC INSULATOR 42572564 Lattice	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <small>Notes:</small>
008/181 41195901 38.445685000000 -121.8257870000		
008/181 CERAMIC INSULATOR 42572565 Lattice	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <small>Notes:</small>
008/182 CERAMIC INSULATOR 40696834 FIELD SWITCH STRUCTURE Lattice	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <small>Notes: OUTSIDE SUB</small>
38.447192000000 -121.8258000000		
008/183 CERAMIC INSULATOR 40626049 DOUBLE VERTICAL Lattice	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <small>Notes:</small>
008/184 40868986 38.448030000000 -121.8257780000		
008/184 CERAMIC INSULATOR 40639666 DOUBLE VERTICAL Lattice	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <small>Notes:</small>
008/185 40816607 38.448819000000 -121.8257700000		
008/185 CERAMIC INSULATOR 40898825 DOUBLE VERTICAL Lattice	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <small>Notes:</small>
008/186 40819575 38.449642000000 -121.8257480000		
008/186 CERAMIC INSULATOR 10893484 DOUBLE VERTICAL Lattice	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <small>Notes:</small>
008/187 40767512 38.450472000000 -121.8257190000		

Transmission Line Object List

Page 24

Inspector Name : COOPER
Date Inspected : 3-26-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
008/187 CERAMIC INSULATOR 40842416 DOUBLE VERTICAL <i>Lattice</i>	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>Replaces Insulators - Pins on Lattice</i> <i>on 1-2 yrs</i>
008/188 40768156 38.451299000000 -121.8245910000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
008/188 CERAMIC INSULATOR 40848018 DOUBLE VERTICAL <i>Lattice</i>	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
008/189 40665509 38.451270000000 -121.8236970000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Notes:
008/189 CERAMIC INSULATOR 40798260 DOUBLE VERTICAL <i>Lattice</i>	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>Replaces Insulators - pins on Lattice</i> <i>OK 1-2 yrs</i>
008/190 40681696 38.451284000000 -121.8226480000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Notes: MONITOR BOTTOM TIE WIRE
008/190 CERAMIC INSULATOR 40799667 DOUBLE VERTICAL <i>Lattice</i>	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
008/191 40592598 38.451516000000 -121.8213130000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Notes:
009/191 CERAMIC INSULATOR 40696838 DOUBLE VERTICAL <i>Lattice</i>	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
008/192 40601216 38.451502500000 -121.8203355000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Notes:
009/192 LATTICE STEEL POLE 1195917 8.451473000000 121.8192910000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>3/20/12</i>
009/193 SINGLE WOOD POLE 0913009 RI PIN ARM <i>✓</i>	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015388
3.452090000000 121.8187680000		
009/194 SINGLE WOOD POLE 0913008 RI PIN ARM <i>✓</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015387
1.452825000000 21.818140000		<i>Pole Spotted ???</i>

Transmission Line Object List

Page 25

Inspector Name : Cooper

Date Inspected : 3-20-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

Medium Impact

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
009/195 SINGLE WOOD POLE 40913007 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015386 MONITOR OLD POLE
38.453274000000 -121.8176840000		
009/196 SINGLE WOOD POLE 40913006 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015385
38.453867000000 -121.8171580000		
009/197 SINGLE WOOD POLE 40913005 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015384 MONITOR OLD SHELL ROTTEN POLE
38.454440000000 -121.8166390000		
009/198 SINGLE WOOD POLE 40913004 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015383
38.455074000000 -121.8160870000		
009/199 SINGLE WOOD POLE 40913003 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015382
38.455681000000 -121.8155450000		
009/200 SINGLE WOOD POLE 40913002 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015381
38.456252000000 -121.8150580000		
009/201 SINGLE WOOD POLE 40913001 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015380
38.456847000000 -121.8145250000		
009/202 SINGLE WOOD POLE 40868353 TRI POST MEDIUM EQP(AERIAL LIFT;LINE TR	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015379
38.457415000000 -121.8140040000		

Transmission Line Object List

Page 26

Inspector Name : Cooper

Date Inspected : 3-20-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
009/203 SINGLE WOOD POLE 40869017 TRI PIN ARM	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>Reframe T-1</i> Notes: '02 Survey: C015378
38.457961000000 -121.8134800000		
009/204 SINGLE WOOD POLE 40816639 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015377 MONITOR SHELL ROTTEN POLE
38.458565000000 -121.8129390000		
009/205 SINGLE WOOD POLE 40817762 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015376
38.459217000000 -121.8123650000		
009/206 SINGLE WOOD POLE 40759673 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015375 MONITOR SHELL ROTTEN POLE
38.459773000000 -121.8118830000		
009/207 SINGLE WOOD POLE 40759920 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015374 MONITOR OLD SHELL ROTTEN POLE
38.460414000000 -121.8113610000		
009/208 SINGLE WOOD POLE 40657546 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015373 <i>Pole Has Wood Stub - Some Crown Rot.</i>
38.461020000000 -121.8107680000		
009/209 SINGLE WOOD POLE 40695635 TRI PIN ARM TRAMP ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015372
38.461564000000 -121.8102500000		
009/210 SINGLE WOOD POLE 40586217 TRI POST ✓ (N/C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015371
38.462188000000 -121.8097450000		

Transmission Line Object List

Page 27

Inspector Name : Cooper

Date Inspected : 3-20-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
010/211 SINGLE WOOD POLE 40677783 TRI POST T-(C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015370
38.462774000000 -121.8091830000 010/212 SINGLE WOOD POLE 40599432 TRI PIN ARM TPA	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015369 MONITOR OLD SHELL ROTTEN POLE - MINOR FIRE DAMAGE
38.463343000000 -121.8087330000 010/213 SINGLE WOOD POLE 40601251 TRI POST T-(N/C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015368
38.463984000000 -121.8081210000 010/214 SINGLE WOOD POLE 40868351 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015367 MINOR ROT
38.464557000000 -121.8076120000 010/215 SINGLE WOOD POLE 40875536 TRI POST T-(C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015366
38.465138000000 -121.8070940000 010/216 SINGLE WOOD POLE 40823512 TRI POST T-(N/C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015365
38.465725000000 -121.8065450000 010/217 SINGLE WOOD POLE 40817760 TRI POST T-(N/C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015364
38.466282000000 -121.8061030000 010/218 SINGLE WOOD POLE 40767542 TRI POST T-(N/C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015363
38.466757000000 -121.8057030000		

Transmission Line Object List

Page 28

Inspector Name : Cooper

Date Inspected : 3-20-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
		Attachment Type/Owner Listed
Equip #	Notes	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
010/219 SINGLE WOOD POLE 40768227 TRI PIN ARM T-1(NC)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015362
38.467105000000 -121.8053710000		
010/220 SINGLE WOOD POLE 40665549 TRI PIN ARM T-1(NC)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015361
38.467675000000 -121.8048710000		
010/221 SINGLE WOOD POLE 40677779 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015360
38.468263000000 -121.8043070000		
010/222 SINGLE WOOD POLE 40592633 TRIANGLE POST 70 T-1(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015359
38.468814000000 -121.8038380000		
010/223 SINGLE WOOD POLE 40601248 TRIANGLE POST 70 T-1 NC	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015358
38.469232000000 -121.8035090000		
010/224 SINGLE WOOD POLE 40874447 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015357
38.469693000000 -121.8030690000		
010/225 SINGLE WOOD POLE 40875499 TRIANGLE POST 70 T-1(c)	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015356
38.470218000000 -121.8026090000		
010/226 SINGLE WOOD POLE 40816637 TRI POST T-1(c)	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015355
38.470778000000 -121.8021100000		

3-20

3-9-12

Transmission Line Object List

Page 29

Inspector Name : Cooper

Date Inspected : 3-9-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
010/227 SINGLE WOOD POLE 40825232 TRI PIN ARM	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015354	Total # of Attachments:
38.471403000000 -121.8015520000		<i>leaning pole < HAS "C" truss installed</i>
010/228 SINGLE WOOD POLE 40767544 TRI PIN ARM <i>T-1 (N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015353	Total # of Attachments:
38.471970000000 -121.8010200000		
010/229 SINGLE WOOD POLE 40759919 TRI POST <i>T-1 (N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015352	Total # of Attachments:
38.472600000000 -121.8004750000		
010/230 SINGLE WOOD POLE 40665552 TRI POST <i>T-1 (N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015351	Total # of Attachments:
38.473167000000 -121.7999940000		
010/231 SINGLE WOOD POLE 40677776 TRIAMP DOUBLE DEAD END <i>3HPD</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015350	Total # of Attachments:
38.473702000000 -121.7995160000		
010/232 SINGLE WOOD POLE 40592632 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015349	Total # of Attachments:
38.474328000000 -121.7989110000		
011/233 SINGLE WOOD POLE 40599434 TRI PIN ARM <i>T-1 (N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015347	Total # of Attachments:
38.474971000000 -121.7983770000		
011/234 SINGLE WOOD POLE 10601245 TRIANGLE POST 70 <i>T-1 (N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015346	Total # of Attachments:
8.475577000000 121.7978540000		

Transmission Line Objec. List

Page 30

Inspector Name : COOPER
 Date Inspected : 3-4-12

Funct Loc : ETL 6740 POLE WOOD 60067 DIXON-VACA #2+ WOOD POLE Medium Impact
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
011/235 SINGLE WOOD POLE 40874427 TRIANGLE POST 70 <i>(Hc)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015345
38.476110000000 -121.7973600000		
011/236 SINGLE WOOD POLE 40869015 TRIANGLE POST 70 <i>(Hc)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015344
38.476740000000 -121.7968030000		
011/237 SINGLE WOOD POLE 40823514 TRI PIN ARM <i>T-1 (NYC)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>R cleaned up pole Debris</i> Notes: '02 Survey: C015343
38.477324000000 -121.7962620000		<i>NEW Pole</i>
011/238 SINGLE WOOD POLE 40825234 TRIANGLE POST 70 <i>T-1 (NYC)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015342
38.477929000000 -121.7957100000		<i>NEW Pole</i>
011/239 SINGLE WOOD POLE 40767568 TRI PIN ARM <i>✓</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015341 <i>MONITOR POLE ~OLD CEDAR, slight Arm rot</i>
38.478470000000 -121.7952260000		
011/240 SINGLE WOOD POLE 40752000 TRI PIN ARM <i>T-1 (NYC)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015340 LEANING MONITOR ONLY
38.479079000000 -121.7946570000		
011/241 SINGLE WOOD POLE 40665553 TRI PIN ARM <i>✓</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015339 LEANING
38.479567500000 -121.7941710000		
011/242 SINGLE WOOD POLE 40695543 TRIPE DOUBLE DEAD END <i>TPA T ramp</i>	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>LEANING Pole - No Change</i> Notes: '02 Survey: C015338 LEANING
38.480309000000 -121.7936190000		

Transmission Line Objec. List

Page 31

Inspector Name : Cooper

Date Inspected : 3-4-12
S

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

Medium Impact

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
		Attachment Type/Owner Listed
Equip #		
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
011/243 SINGLE WOOD POLE 40592630 TRIANGLE POST <i>T-1 (N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>* LEANING Pole - NO CHANGE</i>
38.480863000000 -121.7931050000	Notes: '02 Survey: C015337	LEANING, MINOR
011/244 SINGLE WOOD POLE 40612655 TRI PIN ARM <i>T-1 (N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>ROTTEN Pole</i>
38.481472000000 -121.7925460000	Notes: '02 Survey: C015336	LEANING, MINOR
011/245 SINGLE WOOD POLE 40868349 TRIANGLE POST <i>T-1 (N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>ROTTEN Pole</i>
38.482049000000 -121.7920590000	Notes: '02 Survey: C015335	LEANING, MINOR
011/246 SINGLE WOOD POLE 40869014 TRI PIN ARM <i>T-1 (N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>ROTTEN Pole</i>
38.482653000000 -121.7915160000	Notes: '02 Survey: C015334	
011/247 SINGLE WOOD POLE 40823516 TRI PIN ARM <i>T-1 (N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>ROTTEN Pole</i>
38.483252000000 -121.7909920000	Notes: '02 Survey: C015333	
011/248 SINGLE WOOD POLE 40817758 TRI PIN ARM <i>T-1 (N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>ROTTEN Pole</i>
38.483863000000 -121.7904560000	Notes: '02 Survey: C015332	
011/249 SINGLE WOOD POLE 40767546 TRI PIN ARM <i>T-1 (N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>ROTTEN Pole</i>
38.484438000000 -121.7899360000	Notes: '02 Survey: C015331	
011/250 SINGLE WOOD POLE 40759917 TRI POST <i>T-1 (N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>ROTTEN Pole</i>
38.485043000000 -121.7894150000	Notes: '02 Survey: C015330	

Transmission Line Objec^r List

Page 32

Inspector Name : Cooper

Date Inspected : 3-1-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
011/251 SINGLE WOOD POLE 40665589 TRI PIN ARM ✓	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>X CLEANING POLE - NO CHANGE</i>
38.485624000000 -121.7889010000	Notes: '02 Survey: C015329	
011/252 SINGLE WOOD POLE 40677772 TRI POST T-1 (N/C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
38.486218000000 -121.7883740000	Notes: '02 Survey: C015328	
011/253 SINGLE WOOD POLE 40599467 TRIANGLE POST T-1 (N/C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
38.486798000000 -121.7878480000	Notes: '02 Survey: C015327	
012/254 SINGLE WOOD POLE 40665555 TRIANGLE POST T-0 TH(C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
38.487055000000 -121.7875900000	Notes: '02 Survey: C015326	
012/255 SINGLE WOOD POLE 40695547 TRI POST T-1 (N/C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
38.487393000000 -121.7872930000	Notes: '02 Survey: C015325	
012/256 SINGLE WOOD POLE 40586215 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
38.487990000000 -121.7867730000	Notes: '02 Survey: C015324 <i>Pole Has "C" Truss</i>	
012/257 SINGLE WOOD POLE 40601242 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
38.488577000000 -121.7862480000	Notes: '02 Survey: C015323	
012/258 SINGLE WOOD POLE 40874454 TRIANGLE POST T-0 TH(C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
38.489092000000 -121.7858310000	Notes: '02 Survey: C015322	

Transmission Line Objec. List

Page 33

Inspector Name : Cooper

Date Inspected : 3-5-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
012/259 SINGLE WOOD POLE 4087501 TRI POST ✓ 1-1(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015321
38.489660000000 -121.7853630000		
012/260 SINGLE WOOD POLE 40809775 TRI PIN ARM ✓ MEDIUM EQP(AERIAL LIFT;LINE TR	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015320
38.490263000000 -121.7847670000		
012/261 SINGLE WOOD POLE 40817756 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015319
38.490843000000 -121.7842630000		
012/262 SINGLE WOOD POLE 40767548 TRI PIN ARM TRAMP ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015318
38.491489000000 -121.7836860000		
012/263 SINGLE WOOD POLE 40759914 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015317 ARM NG BOND BROKEN
38.492065000000 -121.7831710000		
012/264 SINGLE WOOD POLE 40657545 TRIANGLE POST ✓ f/c	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015316 MONITOR OLD SHELL ROT POLE
38.492594000000 -121.7826790000		
012/265 SINGLE WOOD POLE 40660483 TRI POST	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015315
38.492949000000 -121.7823280000		
012/266 SINGLE WOOD POLE 40592629 TRI PIN ARM	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Pole Replaced - Hollow Drum MONITOR OLD POLE AND XARM Has osmose stub tag.
38.493504000000 -121.7817490000		

Transmission Line Objec. List

Page 34

Inspector Name : Cooper

Date Inspected : 3-5-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
012/267 SINGLE WOOD POLE 40612717 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015313
38.494063000000 -121.7811120000		
012/268 SINGLE WOOD POLE 40874429 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015312 RE-BOLT BOTTOM BRACE BOLT ON LEG
38.494601000000 -121.7805180000		
012/269 SINGLE WOOD POLE 40869012 TRI PIN ARM ✓ TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015311
38.495149000000 -121.7798880000		
012/270 SINGLE WOOD POLE 40816635 TRIANGLE POST ✓ TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015310
38.495573000000 -121.7794470000		
012/271 SINGLE WOOD POLE 40825191 DOUBLE VERTICAL ✓ TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015309
38.495810000000 -121.7792170000		
012/272 SINGLE WOOD POLE 40759671 TRIANGLE POST ✓ TPA	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 <i>* King Pin Conductor Not Securi-</i> <i>loose Tie wire - EXPEDITE!</i> <i>Temp Repairs made - Clamp top instead</i>
38.495989000000 -121.7790710000		
012/273 SINGLE WOOD POLE 40768189 TRI PIN ARM ✓ T-1 (NY)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015307
38.496577000000 -121.7786160000		
012/274 SINGLE WOOD POLE 40657542 TRI PIN ARM ✓ TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015306
38.497099000000 -121.7782210000		

Transmission Line Objec~~t~~ List

Page 35

Inspector Name : COOPER

Date Inspected : 3-6-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE Medium Impact
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
012/275 SINGLE WOOD POLE 40695552 TRIANGLE POST 70 TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond cked <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015305
38.497664000000 -121.7777560000		
012/276 SINGLE WOOD POLE 40599472 TRIANGLE POST 70 TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond cked <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015304 MONITOR ROTTEN POLE AND STUB <i>(Stub has "C" Truss)</i>
38.498176000000 -121.7773380000		
013/277 SINGLE WOOD POLE 40677768 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond cked <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015302
38.498624000000 -121.7770560000		
013/278 SINGLE WOOD POLE 40592627 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond cked <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015301
38.499073000000 -121.7767790000		
013/279 SINGLE WOOD POLE 40612714 TRIANGLE POST 70 TH-1(NC)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond cked <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015300 POLE NEEDS STUBB
38.499515000000 -121.7765210000		
013/280 SINGLE WOOD POLE 40874431 TRIANGLE POST TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond cked <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015299
38.500020000000 -121.7760980000		
013/281 SINGLE WOOD POLE 40875503 TRIANGLE POST 70 TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond cked <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015298
38.500648000000 -121.7755010000		
013/282 SINGLE WOOD POLE 40816633 TRIANGLE POST 70 TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond cked <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015297
38.501252000000 -121.7750190000		

Transmission Line Object List

Page 36

Inspector Name : COOPER
Date Inspected : 3-6-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE Medium Impact
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments # Attachment Type/Owner Listed
013/283 SINGLE WOOD POLE 40817754 TRIANGLE POST 70 ✓ 38.501781000000 -121.7745220000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015296
013/284 SINGLE WOOD POLE 40767570 FLAT PIN ARM ✓ 38.502385000000 -121.7739410000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015295
013/285 SINGLE WOOD POLE 40768191 TRI PIN ARM ✓ 38.503000000000 -121.7734350000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015294 ✓ Arm HAS SOME ROT, ok This cycle.
013/286 SINGLE WOOD POLE 40665558 TRI PIN ARM ✓ 38.503595000000 -121.7729140000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015293
013/287 SINGLE WOOD POLE 40677764 TRI PIN ARM ✓ 38.504203000000 -121.7723710000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015292
013/288 SINGLE WOOD POLE 40599435 TRI PIN ARM ✓ 38.504792000000 -121.7718820000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015291 ✓ ROTTEN X ARM, 2 yrs
013/289 SINGLE WOOD POLE 40601239 TRI PIN ARM ✓ 38.505233000000 -121.7714260000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015290
013/290 SINGLE WOOD POLE 40868348 TRIANGLE POST 70 ✓ 38.505609000000 -121.7711000000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015289

Transmission Line Objec. List

Page 37

Inspector Name : Cooper
Date Inspected : 3-8-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE Medium Impact
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
013/291 SINGLE WOOD POLE 40869010 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.506230000000 -121.7705500000	Notes: '02 Survey: C015288 <u>12 KV - No. B bows</u>	
013/292 SINGLE WOOD POLE 40816631 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
38.506857000000 -121.7700410000	Notes: '02 Survey: C015287	
013/293 SINGLE WOOD POLE 40825195 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
38.507455000000 -121.7694490000	Notes: '02 Survey: C015286 <u>MONITOR XARM</u>	
013/294 SINGLE WOOD POLE 40759669 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
38.508053000000 -121.7689340000	Notes: '02 Survey: C015285 MONITOR XARM	
013/295 SINGLE WOOD POLE 40768193 TRI PIN ARM ✓	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
MEDIUM EQP(AERIAL LIFT;LINE TR	Notes: '02 Survey: C015284 <u>Pole Replace- Still Bad, Need to Do</u>	
38.508642000000 -121.7684120000	MONITOR SHELL ROT POLE	
013/296 SINGLE WOOD POLE 40665585 TRI POST ✓ T-1 (w/c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
MEDIUM EQP(AERIAL LIFT;LINE TR	Notes: '02 Survey: C015283 <u>NEWER POLE</u>	
38.509216000000 -121.7678830000		
013/297 SINGLE WOOD POLE 40695639 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
MEDIUM EQP(AERIAL LIFT;LINE TR	Notes: '02 Survey: C015282	
38.509837000000 -121.7673300000		
013/298 SINGLE WOOD POLE 40592626 TRI PIN ARM ✓ T-1 (w/o)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
MEDIUM EQP(AERIAL LIFT;LINE TR	Notes: '02 Survey: C015281	
38.510411000000 -121.7668220000		

Transmission Line Object List

Page 38

Inspector Name : Cooper

Date Inspected : 3-8-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
014/299 SINGLE WOOD POLE 40869832 TRI POST <u>T-1(N/C)</u> MEDIUM EQP(AERIAL LIFT;LINE TR	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol	Total # of Attachments: Notes: '02 Survey: C015280
38.511111000000 -121.7662020000		
014/300 SINGLE WOOD POLE 40875505 TRI PIN	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol	Total # of Attachments: <u>REFRAME TO T-1</u> Notes: '02 Survey: C015279
38.511592000000 -121.7657800000		
014/301 SINGLE WOOD POLE 40816629 TRI PIN ARM <u>T-1(N/C)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol	Total # of Attachments: Notes: '02 Survey: C015278
38.512178000000 -121.7652480000		
014/302 SINGLE WOOD POLE 40825197 TRI PIN ARM <u>✓</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol	Total # of Attachments: Notes: '02 Survey: C015277
38.512785000000 -121.7646830000		
014/303 SINGLE WOOD POLE 40752056 FLAT PIN ARM <u>TRIM</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol	Total # of Attachments: MONITOR KARM TOP <u>12KV - NO B. Bond</u> Notes: '02 Survey: C015276
38.513385000000 -121.7641790000		
014/304 SINGLE WOOD POLE 40768195 TRI POST <u>T-1(N/C)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol	Total # of Attachments: 1 PHON-UNKNOWN 1 Notes: '02 Survey: C015275
38.513996000000 -121.7636200000		
014/305 SINGLE WOOD POLE 40657539 TRIANGLE POST 70 <u>T(HC)</u>	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol	Total # of Attachments: 1 PHON-UNKNOWN 1 <u>Pole Replaced - 2010 Scrub Log -</u> <u>12KV - NO B. Bond</u> Notes: '02 Survey: C015274
38.514440000000 -121.7632160000		
014/306 SINGLE WOOD POLE 40695556 TRIANGLE POST 70 <u>T(HC)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol	Total # of Attachments: 1 PHON-UNKNOWN 1 Notes: '02 Survey: C015273
38.514919000000 -121.7627760000		

Transmission Line Object List

Page 39

Inspector Name : Cooper

Date Inspected : 3-8-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE Medium Impact
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
014/307 SINGLE WOOD POLE 40599473 TRIANGLE POST 70 <i>TPAC</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspcrd this patrol	Total # of Attachments: 1 PHON-UNKNOWN 1 Notes: '02 Survey: C015272
38.515377000000 -121.7623490000		
014/308 SINGLE WOOD POLE 40601237 TRI PIN ARM <i>TPAC</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspcrd this patrol	Total # of Attachments: 1 PHON-UNKNOWN 1 Notes: '02 Survey: C015271
38.515661000000 -121.7620670000		
014/309 SINGLE WOOD POLE 40868346 TRIANGLE POST 70 <i>TPAC</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspcrd this patrol	Total # of Attachments: 1 PHON-UNKNOWN 1 <i>* Dry out Bundles Anchor pos.</i> Notes: '02 Survey: C015270
38.516012000000 -121.7617260000		
014/310 SINGLE WOOD POLE 40875534 <i>TPAC</i> (N/C) TRI PIN ARM DEAD END	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspcrd this patrol	Total # of Attachments: 1 PHON-UNKNOWN 1 Notes: '02 Survey: C015269
38.516735000000 -121.7610650000		
014/311 SINGLE WOOD POLE 40823518 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspcrd this patrol	Total # of Attachments: 1 PHON-UNKNOWN 1 Notes: '02 Survey: C015268
38.518286000000 -121.7597080000		
014/312 SINGLE WOOD POLE 40817752 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspcrd this patrol	Total # of Attachments: Notes: '02 Survey: C015267
38.519092000000 -121.7590050000		
014/313 SINGLE WOOD POLE 40759912 TRIANGLE POST 70 <i>TH</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspcrd this patrol	Total # of Attachments: Notes: '02 Survey: C015266
38.519711000000 -121.7584950000		
014/314 SINGLE WOOD POLE 40665561 TRIANGLE POST 70 <i>TH</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspcrd this patrol	Total # of Attachments: Notes: '02 Survey: C015265
38.520180000000 -121.7580920000		

Transmission Line Object List

Page 40

Inspector Name : Cooper
Date Inspected : 3-8-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE Medium Impact
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result [] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not insptd this patrol	Attachments #
		Attachment Type/Owner Listed
		Notes
014/315 SINGLE WOOD POLE 40695560 TRIANGLE POST 70 <i>T H(c)</i>	[X] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not insptd this patrol	Total # of Attachments: Notes: '02 Survey: C015264 MONITOR OLD POLE SHELL ROT
38.520698000000 -121.7576500000		
014/316 SINGLE WOOD POLE 40592624 TRI PIN ARM <i>✓</i>	[] completed/no problems [X] completed/new finding(s) [] pre-existing cond chkd [] not insptd this patrol	Total # of Attachments: <i>REFRAME T-1</i> Notes: '02 Survey: C015263
38.521094000000 -121.7573030000		
015/317 SINGLE WOOD POLE 40602835 FLAT PIN ARM <i>T-1 (N/C)</i>	[X] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not insptd this patrol	Total # of Attachments: Notes: '02 Survey: C015262
38.521668000000 -121.7568280000		
015/318 SINGLE WOOD POLE 40874433 TRIANGLE POST 70 <i>(Tri Pin)</i>	[] completed/no problems [X] completed/new finding(s) [] pre-existing cond chkd [] not insptd this patrol	Total # of Attachments: <i>Reframe T-1</i> Notes: '02 Survey: C015261
38.5222396000000 -121.7561700000		
015/319 SINGLE WOOD POLE 40875540 TRI PIN ARM <i>T-1 (C)</i>	[X] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not insptd this patrol	Total # of Attachments: Notes: '02 Survey: C015260
38.5222974000000 -121.7556600000		
015/320 SINGLE WOOD POLE 40823520 2 HORIZONTAL POST DELTA <i>T-1 (N/C)</i>	[X] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not insptd this patrol	Total # of Attachments: Notes: '02 Survey: C015259
38.5233563000000 -121.7551340000		
015/321 SINGLE WOOD POLE 40817750 TRIANGLE POST 70 <i>TPA(C)</i>	[X] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not insptd this patrol	Total # of Attachments: Notes: '02 Survey: C015258
38.524156000000 -121.7545950000		<i>MINOR ARM ROT</i>
015/322 SINGLE WOOD POLE 40759665 TRI PIN ARM <i>✓</i>	[] completed/no problems [] completed/new finding(s) [X] pre-existing cond chkd [] not insptd this patrol	Total # of Attachments: <i>Pole Replaced - Hollow G/L To 48"</i> Notes: '02 Survey: C015257
38.524753000000 -121.7540560000		

Transmission Line Objec. List

Page 41

Inspector Name : Cooper

Date Inspected : 3-8-12

Funct Loc : ETL 6740 POLE WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
		Attachment Type/Owner Listed
Equip #		
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
015/323 SINGLE WOOD POLE 40768197 TRIANGLE POST 70 TPA (c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015256
38.525315000000 -121.7535300000		
015/324 SINGLE WOOD POLE 40665584 TRIANGLE POST 70 TR-PW(c)	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>* Tri. pin, ReFrame</i> Notes: '02 Survey: C015255
38.525919000000 -121.7530040000		
015/325 SINGLE WOOD POLE 40677760 FIELD SWITCH STRUCTURE TPA	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015254 <i>* Arm has minor rot, 3 grey insul's, no hv</i>
38.526503000000 -121.7524860000		
015/326 SINGLE WOOD POLE 40759667 TRI PIN ARM DVDE (n/c)	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: (2) <i>* Auto Splices IN D-GOYS</i> Notes: '02 Survey: C015253
38.527098000000 -121.7519420000		
015/327 SINGLE WOOD POLE SW 77 40677689 TRI PIN ARM DVDE (n/c)	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>* (1) Auto splice IN D-goys</i> Notes:
38.527152000000 -121.7520010000		
015/328 SINGLE WOOD POLE 40665535 TRIANGLE POST 70 TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: <i>12 KV - NO B BOND</i>
38.526538000000 -121.7525540000		
015/329 SINGLE WOOD POLE 40751991 TRI PIN ARM T-1 (n/c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: <i>12 KV - NO B BOND</i>
38.525977000000 -121.7530460000		
015/330 SINGLE WOOD POLE 40752052 TRIANGLE POST 70 TPA (c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
38.525378000000 -121.7535600000		

Transmission Line Object List

Page 42

Inspector Name : COOPER
Date Inspected : 3-9-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE Medium Impact
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
015/331 SINGLE WOOD POLE 40817718 TRI PIN ARM TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: <i>12KV - NO B. BOND. POLE HAS "C" Truss</i>
38.524775000000 -121.7541140000		
015/332 SINGLE WOOD POLE 40823496 TRI PIN ARM (c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: <i>12 KV - No B. Bond</i>
38.524198000000 -121.7546470000		
015/333 SINGLE WOOD POLE 40868978 TRIANGLE POST 70 3HPD (c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: <i>12KV NO B. BOND</i>
38.523621000000 -121.7551890000		
015/334 SINGLE WOOD POLE 40874413 TRIANGLE POST 70 TPA(c)	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>POLE TEST N/S - Hollow Above 50'</i> <i>Relocate Pole - ELDnBury</i> <i>NEWLY PLANTED FRUIT TREES UNDER LINE</i> <i>UC Davis wastewater plant - NOTIFIED J. MUSSELL</i>
38.523002000000 -121.7557110000		
015/335 SINGLE WOOD POLE 40601204 TRIANGLE POST 70 (H(c))	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: <i>X Arm rolled over.</i>
38.522417000000 -121.7562270000		
015/336 SINGLE WOOD POLE 40599414 FLAT PIN ARM	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>X Arm rolled over.</i>
38.521790000000 -121.7568280000		
016/337 SINGLE WOOD POLE 40599412 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
38.521131000000 -121.7574090000		
016/338 SINGLE WOOD POLE 40695497 TRI PIN ARM	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: <i>38.520804000000 -121.7577310000</i>

Transmission Line Object List

Page 43

Inspector Name : COOPER
Date Inspected : 3-8-92

Funct Loc : ETL 6740 POLE WOOD 60067 DIXON-VACA #2+ WOOD POLE Medium Impact
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
016/339 SINGLE WOOD POLE 40665533 TRI PIN ARM 38.520216000000 -121.7582000000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
016/340 SINGLE WOOD POLE 40759871 TRI PIN ARM 38.519782000000 -121.7585640000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
016/341 SINGLE WOOD POLE 40767530 TRIANGLE POST 70 38.519464000000 -121.7588470000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
016/342 SINGLE WOOD POLE 40825169 TRIANGLE POST 70 38.519152000000 -121.7591560000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: <i>Pole Replace (In house corr) 2 yrs Pecan holes at prim loc</i>
016/343 SINGLE WOOD POLE 40816590 TRI PIN ARM <i>T-1 (N/C)</i> 38.518317000000 -121.7598900000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
016/344 SINGLE WOOD POLE 40868980 TRI PIN ARM <i>TH(c)</i> 38.516828000000 -121.7611830000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
016/345 SINGLE WOOD POLE 40868308 TRIANGLE POST 70 <i>(H/C)</i> 38.516023000000 -121.7619200000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
016/346 SINGLE WOOD POLE 40604074 TRIANGLE POST 70 <i>TPA</i> 38.515707000000 -121.7622080000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:

Transmission Line Object List

Page 44

Inspector Name : Cooper

Date Inspected : 3-8-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
016/347 SINGLE WOOD POLE 40592590 TRIANGLE POST 70 <i>XH(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
38.515464000000 -121.7624650000		
016/348 SINGLE WOOD POLE 40677694 TRIANGLE POST 70 <i>T-1(NC)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
38.514934000000 -121.7628890000		
016/349 SINGLE WOOD POLE 40665531 TRIANGLE POST 70 <i>XH(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
38.514488000000 -121.7632630000		
016/350 SINGLE WOOD POLE 40759873 TRIANGLE POST 70 <i>T-1(NC)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: <i>Has one Burris Anchor -</i>
38.514026000000 -121.7637050000		
016/351 SINGLE WOOD POLE 40767522 FLAT PIN ARM <i>Thump</i>	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>* BROKEN BOND wire.</i> <i>TOP ARM, NORTH Phase</i>
38.513416000000 -121.7642340000		
016/352 SINGLE WOOD POLE 40825175 TRI PIN <i>TP</i>	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>Re-Fix arm T-1</i>
38.512820000000 -121.7647610000		
016/353 SINGLE WOOD POLE 40823494 TRI PIN ARM <i>TP</i> <i>T-1(NC)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: MONITOR XARM
38.512221000000 -121.7653210000		
016/354 SINGLE WOOD POLE 40875483 TRIANGLE POST 70 <i>TP</i> <i>T-1(NC)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
38.511607000000 -121.7658760000		

Transmission Line Object List

Page 45

Inspector Name : COOPER

Date Inspected : 3-8-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
016/355 SINGLE WOOD POLE 40874417 TRI PIN ARM <u>T-1 (n/c)</u> MEDIUM EQP(AERIAL LIFT;LINE TR	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
38.511153000000 -121.7662670000		
017/356 SINGLE WOOD POLE 40592592 TRI PIN ARM <u>T-1 (n/c)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
38.510432000000 -121.7668960000		
017/357 SINGLE WOOD POLE 40695501 TRI PIN ARM <u>T-1 (n/c)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
38.509856000000 -121.7674070000		
017/358 SINGLE WOOD POLE 40657505 TRI PIN ARM <u>T-1 (n/c)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: Pole HAS VERTICLE piece of pole gone! <u>12 KV - NO B.BOND</u>
38.509290000000 -121.7679590000		
017/359 SINGLE WOOD POLE 40768165 TRI PIN ARM	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: <u>Pole Ripped</u> <u>12 KV - NO B.BOND</u>
38.508675000000 -121.7684710000		
017/360 SINGLE WOOD POLE 40759619 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: POLE LEANING - 8/14/2001 <u>MONITOR XARM</u> <u>12 KV - NO B.BOND</u>
38.508100000000 -121.7690050000		
017/361 SINGLE WOOD POLE 40825173 TRI PIN ARM <u>T-1 (n/c)</u>	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: <u>Newer Pole</u>
38.507489000000 -121.7695310000		
017/362 SINGLE WOOD POLE 40816592 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: <u>MONITOR XARM</u> <u>12 KV - NO B.BOND</u>
38.506882000000 -121.7700960000		

Transmission Line Object List

Page 46

Inspector Name : COOPER

Date Inspected : 3-6-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
017/363 SINGLE WOOD POLE 40875475 TRI PIN ARM 38.506258000000 -121.7706100000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>* Dug out Anchor Rod, INSTALLED New guy Marker</i>
017/364 SINGLE WOOD POLE 40868310 TRI PIN ARM ✓ T-1 (N/C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>Notes:</i>
38.505652000000 -121.7711700000		
017/365 SINGLE WOOD POLE 40612607 TRI PIN ARM ✓ 38.505131000000 -121.7716400000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>MINOR X Arm Rot</i>
017/366 SINGLE WOOD POLE 40592594 TRI PIN ARM ✓ 38.504517000000 -121.7721690000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>12KU NO B.Bond.</i>
017/367 SINGLE WOOD POLE 40695477 TRI PIN ARM ✓ 38.503914000000 -121.7726750000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>12KU NO B.Bond</i>
017/368 SINGLE WOOD POLE 40665539 TRI PIN ARM ✓ 38.503328000000 -121.7732180000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>No 12KU B.Bond</i>
017/369 SINGLE WOOD POLE 40759875 TRI PIN ARM ✓A (C) 38.502740000000 -121.7737530000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>No 12KU B.Bond</i>
017/370 SINGLE WOOD POLE 40759621 FLAT PIN ARM ✓amp 38.502156000000 -121.7743030000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>NO 12KU B.BOND</i>

Transmission Line Object List

Page 47

Inspector Name : Cooper

Date Inspected : 3-6-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE Medium Impact
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
017/371 SINGLE WOOD POLE 40825171 TRIANGLE POST 70 <i>(THC)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>12 KV - NO B.BOND</i>
38.501564000000 -121.7748120000	Notes:	
017/372 SINGLE WOOD POLE 40816594 TRIANGLE POST 70 <i>(THC)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>12 KV - NO B.BOND</i>
38.500972000000 -121.7753460000	Notes:	
017/373 SINGLE WOOD POLE 40875477 TRIANGLE POST 70 <i>(TPA)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>12 KV - NO B.BOND</i>
38.500540000000 -121.7757700000	Notes:	
017/374 SINGLE WOOD POLE 40868312 TRIANGLE POST 70 <i>(TPA)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>12 KV - NO B.BOND</i>
38.499994000000 -121.7762200000	Notes:	
017/375 SINGLE WOOD POLE 40612604 TRI PIN ARM <i>(TPA)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>12 KV - NO B.BOND</i>
38.499577000000 -121.7765790000	Notes:	
017/376 SINGLE WOOD POLE 40599420 TRI PIN ARM <i>(TPA)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>X Insulated Vis Strips</i>
38.499122000000 -121.7768650000	Notes:	
017/377 SINGLE WOOD POLE 40677698 TRI PIN ARM <i>(THC)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>X Arm has minor rot</i>
38.498650000000 -121.7771600000	Notes:	
018/378 SINGLE WOOD POLE 40599418 TRIANGLE POST <i>(THC)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>12 KV - NO B.BOND</i>
38.498228000000 -121.7774210000	Notes:	
	<i>12 KV - NO B.BOND</i>	

Transmission Line Object List

Page 48

Inspector Name : Cooper

Date Inspected : 3-5-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments # Attachment Type/Owner Listed
018/379 SINGLE WOOD POLE 40681688 TRIANGLE POST 70 TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes:	Total # of Attachments:
38.497708000000 -121.7778240000		
018/380 SINGLE WOOD POLE 40657507 TRIANGLE POST 70 TPA	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: MONITOR WOOD BRACES * Pole Has "C" Truss	Total # of Attachments:
38.497129000000 -121.7782790000		
018/381 SINGLE WOOD POLE 40768164 TRIANGLE POST 70 T-1 (N/C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes:	Total # of Attachments:
38.496628000000 -121.7786650000		
018/382 SINGLE WOOD POLE 40759623 TRI PIN ARM TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes:	Total # of Attachments:
38.495989000000 -121.7791200000		
018/383 SINGLE WOOD POLE 40825167 TRIANGLE POST 70 TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes:	Total # of Attachments:
38.495783000000 -121.7793320000		
018/384 SINGLE WOOD POLE 40816597 TRIANGLE POST 70 TPB - Double Arms	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: * Some Arm Rot	Total # of Attachments:
38.495615000000 -121.7795090000		
018/385 SINGLE WOOD POLE 40868982 TRIANGLE POST 70 TPA (c)	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: 12 KV - NO B. BOND	Total # of Attachments: * BROKEN BOND Wire - East Phase
38.495196000000 -121.7799430000		
018/386 SINGLE WOOD POLE 40874409 TRI PIN ARM T-1 (N/C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: NEWER POLE	Total # of Attachments: * Clean up old pole Debris
38.494645000000 -121.7805710000		

Transmission Line Object List

Page 49

Inspector Name : COOPER

Date Inspected : 3-5-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments # Attachment Type/Owner Listed
018/387 SINGLE WOOD POLE 40612613 TRI PIN ARM ✓	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: X BROKEN BOND WIRE - EAST Phase
38.494105000000 -121.7811620000	Notes:	
018/388 SINGLE WOOD POLE 40599408 TRIANGLE POST 70 ✓ TPA	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: * INSTALLED GUY MARKER
38.493553000000 -121.7817880000	Notes: 12 KU - NO B.BOND	
018/389 SINGLE WOOD POLE 40677702 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: * INSTALLED GUY MARKER
38.492990000000 -121.7823960000	Notes: Pole is OUT - will need to be Replaced	
018/390 SINGLE WOOD POLE 40665514 TRIANGLE POST 70 ✓	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Replace Pole
38.492636000000 -121.7827610000	Notes:	
018/391 SINGLE WOOD POLE 40759877 TRI PIN ARM ✓	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: leaning Pole - NO CHANGE
38.492113000000 -121.7832240000	Notes: 12 KU - NO B.BOND	
018/392 SINGLE WOOD POLE 40767518 TRI PIN ARM TRAMP ✓	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: leaning Pole - Complete Pole Has "C" Thru Truss Installed
38.491542000000 -121.7837560000	Notes: DISTRIBUTION PT 6 SQUATER.	
018/393 SINGLE WOOD POLE 40825159 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: * Arm HAS minor Rot
38.490887000000 -121.7843070000	Notes: 12 KU - NO B.BOND	
018/394 SINGLE WOOD POLE 40823490 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
38.490288000000 -121.7848410000		

Transmission Line Object List

Page 50

Inspector Name : Cooper

Date Inspected : 3-5-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE Medium Impact
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
018/395 SINGLE WOOD POLE 40875469 TRI POST <i>TPAC</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 12 KV - NO B. Bond
38.489702000000 -121.7853590000	Notes:	
018/396 SINGLE WOOD POLE 40874403 TRIANGLE POST <i>TPA</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 12 KV - NO B. Bond
38.489134000000 -121.7858590000	Notes:	
018/397 SINGLE WOOD POLE 40601207 TRI PIN ARM <i>T-1(N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 12 KV - NO B. Bond
38.488633000000 -121.7862980000	Notes:	
018/398 SINGLE WOOD POLE 41121534 TRIANGLE POST <i>TAC(C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 12 KV - NO B. Bond
38.488056000000 -121.7868190000	Notes:	
018/399 SINGLE WOOD POLE 40599411 TRI PIN ARM <i>TH(C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 12 KV - NO B. Bond
38.487548000000 -121.7872960000	Notes:	
019/400 SINGLE WOOD POLE 40677706 TRIANGLE POST <i>T-1(N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 12 KV - NO B. Bond
38.487176000000 -121.7876050000	Notes:	
019/401 SINGLE WOOD POLE 40599403 TRI PIN ARM <i>✓</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 12 KV - NO B. Bond
38.486829000000 -121.7879250000	Notes:	
019/402 SINGLE WOOD POLE 40642982 TRIANGLE POST <i>TPR</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: * INSTALLED NEW Guy Marker
38.486243000000 -121.7884000000	Notes:	

Transmission Line Object List

Page 51

Inspector Name : COOPER

Date Inspected : 3-9-12

5

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
019/403 SINGLE WOOD POLE 40650170 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: 12 KV - No B.Bond
38.485669000000 -121.7889210000		
019/404 SINGLE WOOD POLE 40759879 TRI PIN ARM TH(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: 12 KV - No B.Bond
38.485096000000 -121.7894410000		
019/405 SINGLE WOOD POLE 40759625 TRI PIN ARM T-1 (N/C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: NEW Pole
38.484464000000 -121.7900000000		
019/406 SINGLE WOOD POLE 40825157 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: 12 KV - No B.Bond
38.483903000000 -121.7904860000		
019/407 SINGLE WOOD POLE 40816599 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: 12 KV - No B.Bond
38.483376000000 -121.7910710000		
019/408 SINGLE WOOD POLE 40875467 TRI PIN ARM TH(c)	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: CLEANING Pole - NO Change
38.482711000000 -121.7916670000		
019/409 SINGLE WOOD POLE 40874405 TRIANGLE POST 70	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: DIST SQUATER WEST PH CLEANING Pole - NO Change
38.482097000000 -121.7921530000		
019/410 SINGLE WOOD POLE 40612598 TRI PIN ARM	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: DIST SQUATER WEST PH * ROTTEN X ARM BRACE, MINOR ARM ROT. 6-MONS CLEANING Pole - NO Change
38.481535000000 -121.7926510000		

Transmission Line Object List

Page 52

Inspector Name : Cooper

Date Inspected : 3-4-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
019/411 SINGLE WOOD POLE 40599405 TRIANGLE POST 70 TPA(c) 38.480894000000 -121.7932220000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>* LEANING Pole - NO CHANGE</i>
019/412 SINGLE WOOD POLE 40677711 TRI PIN ARM TRAMP 3HPD(c) 38.480329000000 -121.7937190000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>* X ARM HAS MINOR ROT</i> <i>* LEANING POLE - NO CHANGE</i>
019/413 SINGLE WOOD POLE 40665518 TRI PIN ARM T-1(c) 38.479748000000 -121.7942460000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>* LEANING POLE - NO CHANGE</i>
019/414 SINGLE WOOD POLE 40761767 TRI PIN ARM T-1(c) 38.479146000000 -121.7947560000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
019/415 SINGLE WOOD POLE 40767516 TRI PIN ARM T-1(c) 38.478531000000 -121.7953120000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
019/416 SINGLE WOOD POLE 40817720 TRIANGLE POST 70 TPA 38.477965000000 -121.7958100000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: <i>12KV</i> <i>NO B.BOND</i>
019/417 SINGLE WOOD POLE 40816601 TRI PIN ARM T-1 nk 38.477378000000 -121.7963210000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: <i>12KV</i> <i>NO B.BOND</i>
A003/079 SINGLE WOOD POLE 40768140 FLAT PIN ARM 38.385685000000 -121.8777960000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 X Arm

Transmission Line Objec. List

Page 53

Inspector Name : Cooper

Date Inspected : 3-19-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
A003/080 SINGLE WOOD POLE 40767520 TRI PIN ARM DEAD END 38.385176000000 -121.8782310000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015955	Total # of Attachments:
A004/081 SINGLE WOOD POLE SW 49 40817778 FIELD SWITCH STRUCTURE 38.384753000000 -121.8786220000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes:	Total # of Attachments:
A004/082 SINGLE WOOD POLE 40823472 TRI POST 38.384243000000 -121.8790800000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015957	Total # of Attachments:
A004/083 SINGLE WOOD POLE 40869030 TRI POST 38.383679000000 -121.8795750000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015958	Total # of Attachments:
A004/084 SINGLE WOOD POLE 40874383 3 HORIZONTAL POST DELTA SHORT 38.383084000000 -121.8800830000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015959	Total # of Attachments:
A004/085 SINGLE WOOD POLE 40601259 TRI POST 38.382499000000 -121.8806150000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015960	Total # of Attachments:
A004/086 SINGLE WOOD POLE 41122286 TRI POST 38.381897000000 -121.8811540000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015961	Total # of Attachments:
A004/087 SINGLE WOOD POLE 40592640 TRI POST 38.381290000000 -121.8816820000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: C015962	Total # of Attachments:

Transmission Line Objec. List

Page 54

Inspector Name : COOPER
Date Inspected : 3/9/12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE Medium Impact
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
A004/088 SINGLE WOOD POLE 40677818 TRI POST T-1(c) 38.380695000000 -121.8821830000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015963
A004/089 SINGLE WOOD POLE 40665500 TRI POST T-1(c) 38.380245000000 -121.8825890000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015964
A004/090 SINGLE WOOD POLE 40768158 TRI POST T-1(c) 38.380038000000 -121.8827590000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015965
A004/091 SINGLE WOOD POLE 40767500 TRI POST T-1(c) 38.379525000000 -121.8832790000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015966
A004/092 SINGLE WOOD POLE 40817780 TRI POST T-1(c) 38.378931000000 -121.8837800000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015967
A004/093 SINGLE WOOD POLE 40823470 TRI POST T-1(NC) 38.378333000000 -121.8843000000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015968
A004/094 SINGLE WOOD POLE 40875452 TRI POST T-1(NC) 38.377746000000 -121.8848280000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015969
A004/095 SINGLE WOOD POLE 40868364 TRI POST T-1(c) 38.377127000000 -121.8853990000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015970

Transmission Line Object List

Page 55

Inspector Name : COOPER

Date Inspected : 3-19-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE Medium Impact
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
		Attachment Type/Owner Listed
Equip #	Notes	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
A004/096 SINGLE WOOD POLE 40612577 TRI POST T-(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015971
38.376540000000 -121.8859100000		
A004/097 SINGLE WOOD POLE 40592642 TRI POST T-1(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015972
38.375998000000 -121.8863920000		
A004/098 SINGLE WOOD POLE 40695439 TRI POST T-1(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015973
38.375362000000 -121.8869560000		
A004/099 SINGLE WOOD POLE 40665485 3 HORIZONTAL POST DELTA SHORT	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015974
38.374741000000 -121.8875160000		
A004/100 SINGLE WOOD POLE 40759930 TRI POST T-1(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015975
38.374164000000 -121.8880300000		
A004/101 SINGLE WOOD POLE 40759686 TRI POST T-1 (N/C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015976
38.373597000000 -121.8885600000		
A005/102 SINGLE WOOD POLE 40817782 TRI POST T-1(c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015977
38.373005000000 -121.8890820000		
A005/103 SINGLE WOOD POLE 40816647 TRI POST T-1 (N/C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015978
38.372416000000 -121.8896040000		

Transmission Line Object List

Page 56

Inspector Name : COOPER

Date Inspected : 3-19-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
A005/104 SINGLE WOOD POLE 40869032 TRI POST <i>T-1(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015979
38.371842000000 -121.8901470000		
A005/105 SINGLE WOOD POLE 40874369 TRI POST <i>T-1(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015980
38.371216000000 -121.8906670000		
A005/106 SINGLE WOOD POLE 40612567 TRI POST <i>T-1(c)</i>	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>* Brown Insul's Kpin' N. phase.</i> Notes: '02 Survey: C015981
38.370593000000 -121.8912310000		
A005/107 SINGLE WOOD POLE 40599365 TRI POST <i>T-1(N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015982
38.370048000000 -121.8917130000		
A005/108 SINGLE WOOD POLE 40695406 TRI POST <i>T-1(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015983
38.369398000000 -121.8922370000		
A005/109 SINGLE WOOD POLE 40665477 TRI POST <i>T-1(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015984
38.368828000000 -121.8927510000		
A005/110 SINGLE WOOD POLE 40759932 TRI POST <i>T-1(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015985
38.368224000000 -121.8932580000		
A005/111 SINGLE WOOD POLE 40767488 TRI POST <i>T-1(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015986
38.367613000000 -121.8938180000		

Transmission Line Object List

Page 57

Inspector Name : COOPER

Date Inspected : 3-19-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
A005/112 SINGLE WOOD POLE 40817784 TRI POST <u>T-1(c)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015987
38.367034000000 -121.8943290000		
A005/113 SINGLE WOOD POLE 40823443 TRI POST <u>T-1(c)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015988
38.366317000000 -121.8949920000		
A005/114 SINGLE WOOD POLE 40869034 TRI POST <u>T-1(c)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015989
38.365849000000 -121.8954190000		
A005/115 SINGLE WOOD POLE 40874367 3 HORIZONTAL POST DELTA ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015990
38.365269000000 -121.8958990000		
A005/116 SINGLE WOOD POLE 40601262 TRI POST <u>T-1(c)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015991
38.364657000000 -121.8964260000		
A005/117 SINGLE WOOD POLE 40599363 TRI POST <u>T-1(c)</u>	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015992
38.364334000000 -121.8967080000		
A005/118 SINGLE WOOD POLE 40695435 TRI POST	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 FIBR-UNKNOWN 1 Notes: '02 Survey: C015993
38.364064000000 -121.8969720000		
A005/119 SINGLE WOOD POLE 40665475 TRI POST	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 FIBR-UNKNOWN 1 Notes: '02 Survey: C015994
38.363502000000 -121.8975040000		

Transmission Line Object List

Page 58

Inspector Name : COOPER
 Date Inspected : 3-28-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE Medium Impact
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result	Attachments #
		Attachment Type/Owner Listed
A005/120 SINGLE WOOD POLE 40759934 TRI POST 38.362989000000 -121.8979610000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 FIBR-UNKNOWN 1 Notes: '02 Survey: C015995
A005/121 SINGLE WOOD POLE 40767486 TRI POST 38.362487000000 -121.8983800000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 FIBR-UNKNOWN 1 Notes: '02 Survey: C015996
A005/122 SINGLE WOOD POLE 40825139 TRI POST 38.361765000000 -121.8990010000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 FIBR-UNKNOWN 1 Notes: '02 Survey: C015997
A006/123 SINGLE WOOD POLE 40823455 TRI POST 38.361075000000 -121.8996160000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 FIBR-UNKNOWN 1 LEANING Pole Notes: '02 Survey: C015998
A006/124 SINGLE WOOD POLE 40869036 TRI POST 38.360497000000 -121.9001440000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 FIBR-UNKNOWN 1 LEANING Pole Notes: '02 Survey: C015999
A006/125 SINGLE WOOD POLE 40874365 TRI POST 38.359913000000 -121.9006320000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 FIBR-UNKNOWN 1 LEANING Pole Notes: '02 Survey: C016000
A006/126 SINGLE WOOD POLE 40601265 TRI POST 38.359500000000 -121.9011000000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 FIBR-UNKNOWN 1 Notes: '02 Survey: C016001
A006/127 SINGLE WOOD POLE 40592643 TRI POST 38.358993000000 -121.9014910000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 FIBR-UNKNOWN 1 LEANING Pole Notes: '02 Survey: C016002

Transmission Line Object List

Page 59

Inspector Name : Cooper

Date Inspected : 3-28-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
A006/128 SINGLE WOOD POLE 40677822 TRI POST 38.358730000000 -121.9017240000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 FIBR-UNKNOWN 1 Notes: '02 Survey: C016003
A006/129 SINGLE WOOD POLE 40599362 TRI POST 38.358133000000 -121.9022380000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 FIBR-UNKNOWN 1 Notes: '02 Survey: C016004
A006/130 SINGLE WOOD POLE 40695373 TRI POST 38.357575000000 -121.9027670000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 FIBR-UNKNOWN 1 Notes: '02 Survey: C016005
A006/131 SINGLE WOOD POLE 40657554 TRI POST 38.356974000000 -121.9032510000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 FIBR-UNKNOWN 1 Notes: '02 Survey: C016006
A006/132 SINGLE WOOD POLE 40768115 TRI POST 38.356378000000 -121.9038000000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 FIBR-UNKNOWN 1 Notes: '02 Survey: C016007
A006/133 SINGLE WOOD POLE 40759688 3 HORIZONTAL POST DELTA SHORT 38.355764000000 -121.9043450000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 FIBR-UNKNOWN 1 Notes: '02 Survey: C016008
A006/134 SINGLE WOOD POLE 40825133 TRI POST 38.355094000000 -121.9049290000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 FIBR-UNKNOWN 1 Notes: '02 Survey: C016009
A006/135 SINGLE WOOD POLE 40823453 TRI POST 38.354600000000 -121.9054060000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 2 DIST-0310456 1; FIBR-UNKNOWN 1 Notes: '02 Survey: C016010

Transmission Line Object List

Page 60

Inspector Name : Cooper
 Date Inspected : 3-29-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE Medium Impact
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
A006/136 SINGLE WOOD POLE 40875432 TRI POST 38.353984000000 -121.9058970000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 2 DIST-0310456 1; FIBR-UNKNOWN 1 Notes: '02 Survey: C016011
A006/137 SINGLE WOOD POLE 40868366 ANGLE 0-30 DEGREES 38.353616000000 -121.9061300000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 2 DIST-0310456 1; FIBR-UNKNOWN 1 Notes: '02 Survey: C016012
A006/138 SINGLE WOOD POLE 40612555 TRI POST 38.353200000000 -121.9060920000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 2 DIST-0310456 1; FIBR-UNKNOWN 1 Notes: '02 Survey: C016013
A006/139 SINGLE WOOD POLE 40599379 TRI POST 38.352527000000 -121.9060760000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 2 DIST-0310456 1; FIBR-UNKNOWN 1 Notes: '02 Survey: C016014
A006/140 SINGLE WOOD POLE 40695369 TRI POST 38.351891000000 -121.9061000000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 2 DIST-0310456 1; FIBR-UNKNOWN 1 Notes: '02 Survey: C016015
A006/141 SINGLE WOOD POLE 40657556 TRI POST 38.351543000000 -121.9062110000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 3 DIST-0310456 1; FIBR-UNKNOWN 1; STLT-UNKNOWN 1 Notes: '02 Survey: C016016 STREET LIGHT
A006/142 SINGLE WOOD POLE 40759936 TRI POST 38.351313000000 -121.9062460000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 3 DIST-0310456 1; FIBR-UNKNOWN 1; PHON-UNKNOWN 1 Notes: '02 Survey: C016017
A006/143 SINGLE WOOD POLE 40759690 TRI POST 38.350994000000 -121.9065370000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 3 DIST-0310456 1; FIBR-UNKNOWN 1; PHON-UNKNOWN 1 Notes: '02 Survey: C016018 <i>Replace Pole</i>

Transmission Line Object List

Page 61

Inspector Name : Cooper
 Date Inspected : 3-28-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE Medium Impact
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
A006/144 SINGLE WOOD POLE 40825141 TRI POST 38.350581000000 -121.9068830000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 3 DIST-0310456 1; FIBR-UNKNOWN 1; PHON-UNKNOWN 1 Notes: '02 Survey: C016019
A006/145 SINGLE WOOD POLE 40816649 TRI POST 38.350302000000 -121.9071680000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 4 DIST-0310456 2; FIBR-UNKNOWN 1; PHON-UNKNOWN 1 Notes: '02 Survey: C016020
A006/146 SINGLE WOOD POLE 40875430 TRI POST 38.349923000000 -121.9075730000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 3 DIST-0310456 2; FIBR-UNKNOWN 1 Notes: '02 Survey: C016021
A006/147 SINGLE WOOD POLE 40868368 TRI POST 38.349633000000 -121.9077420000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 4 DIST-0310456 2; FIBR-UNKNOWN 1; PHON-UNKNOWN 1 Notes: '02 Survey: C016022
A007/148 SINGLE WOOD POLE 40612552 TRI POST 38.349320000000 -121.9080070000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 5 DIST-0310456 2; FIBR-UNKNOWN 1; PHON-UNKNOWN 1; STLT-UNKNOWN 1 Notes: '02 Survey: C016023 STREET LIGHT
A007/149 SINGLE WOOD POLE 40592645 TRI POST 38.348887000000 -121.9083170000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 3 DIST-0310456 2; FIBR-UNKNOWN 1 Notes: '02 Survey: C016024
A007/150 SINGLE WOOD POLE 40695365 TRI POST 38.348493000000 -121.9086470000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 5 DIST-0310456 2; FIBR-UNKNOWN 1; PHON-UNKNOWN 1; STLT-UNKNOWN 1 Notes: '02 Survey: C016025 STREET LIGHT
A007/151 SINGLE WOOD POLE 40657558 TRI POST 38.348124000000 -121.9090980000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 3 DIST-0310456 1; FIBR-UNKNOWN 1; STLT-UNKNOWN 1 Notes: '02 Survey: C016026 STREET LIGHT

Transmission Line Object List

Page 62

Inspector Name : COOPER
Date Inspected : 3-23-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
A007/152 SINGLE WOOD POLE 40768138 DOUBLE VERTICAL 38.347694000000 -121.9094020000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 3 DIST-0310456 1; FIBR-UNKNOWN 1; STLT-UNKNOWN 1 Notes: '02 Survey: C016027 STREET LIGHT
A007/153 SINGLE WOOD POLE 40759692 TRI POST 38.347774000000 -121.9097330000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 FIBR-UNKNOWN 1 Notes: '02 Survey: C016028
A007/154 SINGLE WOOD POLE 40825131 TRI POST 38.347890000000 -121.9106250000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 FIBR-UNKNOWN 1 Notes: '02 Survey: C016029
A007/155 SINGLE WOOD POLE 40816651 DOUBLE VERTICAL 38.347981000000 -121.9111870000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>Install shorts over Guy Auto Splices</i> Notes: '02 Survey: C016030
A007/156 SINGLE WOOD POLE 41122288 TRI POST T-1(c) 38.347430000000 -121.9116820000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>X</i> Notes: '02 Survey: C016031
A007/157 SINGLE WOOD POLE 41122290 TRI POST T-1(c) 38.346926000000 -121.9121810000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>X Re-ATTACHED Pipe Fiber Optic</i> <i>To Pole.</i> Notes: '02 Survey: C016032
A007/158 SINGLE WOOD POLE 40592646 TRI POST T-1(c) 38.346342000000 -121.9127240000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016033
A007/159 SINGLE WOOD POLE 40695360 TRI POST T-1(c) 38.345774000000 -121.9132450000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016034

Transmission Line Object List

Page 63

Inspector Name : COOPER

Date Inspected : 3-23-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
A007/160 SINGLE WOOD POLE 40665473 TRI POST T-(C) 38.345149000000 -121.9137450000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016035
A007/161 SINGLE WOOD POLE 40768130 TRI POST T-(C) 38.344576000000 -121.9142740000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016036
A007/162 SINGLE WOOD POLE 40767483 3 HORIZONTAL POST DELTA SHORT 3 HPS 38.343991000000 -121.9148100000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016037
A007/163 SINGLE WOOD POLE 40817786 TRI POST T-(C) 38.343545000000 -121.9151840000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016038
A007/164 SINGLE WOOD POLE 40823442 TRI POST T-(C) 38.342928000000 -121.9157440000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016039
A007/165 SINGLE WOOD POLE 40875436 TRI POST T-(C) 38.342632000000 -121.9159730000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016040
A007/166 SINGLE WOOD POLE 40874363 TRI POST T-(C) 38.342015000000 -121.9165270000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016041
A007/167 SINGLE WOOD POLE 40601267 TRI POST T-(C) 38.341395000000 -121.9170350000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016042

Transmission Line Object List

Page 64

Inspector Name : COOPER
Date Inspected : 3-23-72

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
A007/168 SINGLE WOOD POLE 40599360 3 HORIZONTAL POST DELTA SHORT 38.340769000000 -121.9176070000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016043
A007/169 SINGLE WOOD POLE 40677826 TRI POST 38.340240000000 -121.9180670000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016044
A007/170 SINGLE WOOD POLE 40665469 TRI POST 38.339618000000 -121.9186460000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016045
A007/171 SINGLE WOOD POLE 40759938 TRI POST 38.338969000000 -121.9192000000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016046
A007/172 SINGLE WOOD POLE 40767480 TRI POST 38.338374000000 -121.9197410000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016047
A007/173 SINGLE WOOD POLE 40817788 TRI POST 38.337812000000 -121.9202320000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016048 <i>* Missing Crossing Marker</i>
A008/174 SINGLE WOOD POLE 40823468 TRI POST 38.337249000000 -121.9207130000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C016049
A008/175 SINGLE WOOD POLE 40869038 TRI POST 38.336580000000 -121.9213590000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C016050

Transmission Line Object List

Page 65

Inspector Name : Coopen
Date Inspected : 3-23-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
A008/176 SINGLE WOOD POLE 40599359 TRI POST 38.335944000000 -121.9219730000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C016051
A008/177 SINGLE WOOD POLE 40677830 TRI POST 38.335289000000 -121.9226010000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C016052
A008/178 SINGLE WOOD POLE 40665471 TRI POST 38.334618000000 -121.9231630000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C016053
A008/179 SINGLE WOOD POLE 40768122 TRI POST 38.334026000000 -121.9237710000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C016054
A008/180 SINGLE WOOD POLE 40767482 TRI POST 38.333372000000 -121.9242700000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C016055
A008/181 SINGLE WOOD POLE 40817790 TRI POST 38.332800000000 -121.9247840000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C016056
A008/182 SINGLE WOOD POLE 40823464 TRI POST 38.332197000000 -121.9253210000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C016057
A008/183 SINGLE WOOD POLE 40869040 TRI POST 38.331621000000 -121.9258370000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C016058

SLIGHT LEAN-WEST

Transmission Line Object List

Page 66

Inspector Name : Cooper

Date Inspected : 3-23-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE Medium Impact
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
A008/184 SINGLE WOOD POLE 40868370 TRI POST T-1(C) 38.331003000000 -121.9263830000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C016059
A008/185 SINGLE WOOD POLE 40601269 TRI POST T-1 (N/C) 38.330403000000 -121.9269190000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C016060
A008/186 SINGLE WOOD POLE 40599376 TRI POST T-1(C) 38.329750000000 -121.9274760000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C016061
A008/187 SINGLE WOOD POLE 40677835 TRI POST T-1(C) 38.329231000000 -121.9279340000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C016062
A008/188 SINGLE WOOD POLE 40665467 TRI POST T-1(C) 38.328614000000 -121.9284640000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C016063 <i>Pole Has "C" Truss</i>
A008/189 SINGLE WOOD POLE 40759940 TRI POST T-1(C) 38.328054000000 -121.9290160000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016064 <i>Pole Has "C" Truss</i>
A008/190 SINGLE WOOD POLE 40767477 TRI POST T-1(N/C) 38.327409000000 -121.9295830000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016065
A008/191 SINGLE WOOD POLE 40817792 TRI POST T-1(C) 38.326824000000 -121.9300770000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016066 <i>Pole Has "C" Truss</i>

Transmission Line Object List

Page 67

Inspector Name : Cooper

Date Inspected : 3-23-17

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
A008/192 SINGLE WOOD POLE 40823440 TRI POST <i>T-1(C)</i> 38.326234000000 -121.9306140000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016067
A009/193 SINGLE WOOD POLE 40869042 TRI POST <i>T-1(C)</i> 38.325572000000 -121.9311310000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016068
A009/194 SINGLE WOOD POLE 40874361 TRI POST <i>T-1(C)</i> 38.325039000000 -121.9316290000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016069
A009/195 SINGLE WOOD POLE 40601272 TRI POST <i>T-1(C)</i> 38.324454000000 -121.9321860000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016070
A009/196 SINGLE WOOD POLE 40599357 1 VERTICAL SHORT POST <i>3H8P(C)</i> 38.323900000000 -121.9327480000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016071
A009/197 SINGLE WOOD POLE 40599380 TRI POST <i>T-1(C)</i> 38.323310000000 -121.9332620000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016072
A009/198 SINGLE WOOD POLE 40695356 VERT POST <i>T-1(C)</i> 38.322640000000 -121.9338660000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016073
A009/199 SINGLE WOOD POLE 40665465 TRI POST 38.322382000000 -121.9340040000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016074

Transmission Line Object List

Page 68

Inspector Name : COOPER
 Date Inspected : 2-24-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
 Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
A009/200 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
40768124		
TRI POST		
38.321806000000		
-121.9345330000		
A009/201 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
40759694		
TRI POST		
38.321250000000		
-121.9350620000		
A009/202 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
40825129		
TRI POST		
38.320653000000		
-121.9355620000		
A009/203 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
40816653		
TRI POST		
38.319992000000		
-121.9361230000		
A009/204 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
40875429		
TRI POST		
38.319407000000		
-121.9366990000		
A009/205 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
40868372		
TRI POST		
38.318799000000		
-121.9371750000		
A009/206 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
40601275		
TRI POST		
38.318246000000		
-121.9376920000		
A009/207 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
40599356		
TRI POST		
38.317655000000		
-121.9382390000		

Transmission Line Object List

Page 69

Inspector Name : COOPER
Date Inspected : 2-24-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
A009/208 SINGLE WOOD POLE 40677839 TRI POST 38.317080000000 -121.9387400000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016083
A009/209 SINGLE WOOD POLE 40665496 TRI POST 38.316515000000 -121.9392310000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016084
A009/210 SINGLE WOOD POLE 40768126 TRI POST 38.316004000000 -121.9396160000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016085 <i>Pole Has "C" Truss</i>
A009/211 SINGLE WOOD POLE 40767475 TRI POST 38.315671000000 -121.9399820000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016086
A009/212 SINGLE WOOD POLE 40825127 TRI POST 38.315111000000 -121.9404290000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016087
A009/213 SINGLE WOOD POLE 40816655 TRI POST 38.314649000000 -121.9408150000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016088 <i>Pole Has "C" Truss</i>
A009/214 SINGLE WOOD POLE 40875427 TRI POST 38.314243000000 -121.9411090000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016089
A010/215 SINGLE WOOD POLE 40868374 TRI POST 38.313557000000 -121.9416300000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016090 <i>Pole Has "C" Truss</i>

Transmission Line Object List

Page 70

Inspector Name : COOPER

Date Inspected : 3-23-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
A010/216 SINGLE WOOD POLE 40612549 TRI POST 38.313088000000 -121.9419650000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>* Trimmed out tree</i> Notes: '02 Survey: C016091
A010/217 SINGLE WOOD POLE 40592648 TRI POST 38.312570000000 -121.9423280000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016092
A010/218 SINGLE WOOD POLE 40677842 TRI POST 38.311951000000 -121.9427380000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016093
A010/219 SINGLE WOOD POLE 40599382 TRI POST 38.311409000000 -121.9430450000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016094
A010/220 SINGLE WOOD POLE 40677846 TRI POST 38.310789000000 -121.9434210000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016095
A010/221 SINGLE WOOD POLE 40657560 TRI POST T-1(c) 38.310137000000 -121.9438270000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016096
A010/222 SINGLE WOOD POLE 40768111 ANGLE 0-30 DEGREES SV 38.309471000000 -121.9439840000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016097
A010/223 SINGLE WOOD POLE 40767496 1 VERTICAL SHORT POST 3HPP(c) 38.308824000000 -121.9443680000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016098

Transmission Line Object List

Page 71

Inspector Name : COOPER
Date Inspected : 3-23-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
A010/224 SINGLE WOOD POLE 40825125 TRI POST T-(C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016099
38.308308000000 -121.9446900000		
A010/225 SINGLE WOOD POLE 40816657 TRI POST T-(C)	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>*(2) Auto Splices At Pole. Middle Phase</i>
38.307575000000 -121.9451490000		
A010/226 SINGLE WOOD POLE 40875425 TRI POST T-(C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016101
38.307023000000 -121.9454700000		
A010/227 SINGLE WOOD POLE 40868375 TRI POST T-(C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016102
38.306315000000 -121.9458830000		
A010/228 SINGLE WOOD POLE 40612574 TRI POST T-(C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016103
38.305737000000 -121.9462360000		
A010/229 SINGLE WOOD POLE 40592649 TRI POST T-(C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016104
38.305053000000 -121.9465820000		
A010/230 SINGLE WOOD POLE 40695414 TRI POST T-(C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016105
38.304445000000 -121.9468820000		
A010/231 SINGLE WOOD POLE 40657561 TRI POST T-(C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016106
38.303766000000 -121.9473620000		

Transmission Line Objec. List

Page 72

Inspector Name : COOPER

Date Inspected : 3-23-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE
 Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
A010/232 SINGLE WOOD POLE 40768113 TELE POST T-1(C) 38.303171000000 -121.9477190000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C016107
A010/233 SINGLE WOOD POLE SW 27 40759696 FIELD SWITCH STRUCTURE MEDIUM EQP(AERIAL LIFT;LINE TR TRAVERS SCT 38.302519000000 -121.9481360000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
B007/179 SINGLE WOOD POLE 41122279 FLAT PIN ARM 38.445045000000 -121.8259260000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015771

○ - On Time
 □ - Due 3
 △ - Due 4

Notification	Notification type	Priority	Priority Description	Description	Main WorkCtr	Notification Date	Due Date	Completion Date	Order	Open/Closed	Past Due
111749507	LC	E	E - Schd Compl Yr 0	BELLOTA-WEBER 13/90 VEG	VICTOR	6/23/2016	6/23/2017		Open	No	
111748937	LC	E	E - Schd Compl Yr 0	BELLOTA-WEBER 4/32 HV	VICTOR	06/23/2016	06/23/2017	07/28/2016	42733443	Closed	No
111748938	LC	E	E - Schd Compl Yr 0	BELLOTA-WEBER 6/43 CLIMB GUARD	VICTOR	6/23/2016	6/23/2017		31250356	Open	No
111305855	LC	E	E - Schd Compl Yr 0	BELLOTA-WEBER 12/86 BENT STEEL MEMBER	VICTOR	01/13/2016	01/13/2017	02/18/2016	4263130	Closed	No
111742077	LC	B	B - Urgt Compliance	BELLOTA-WEBER-TOWER 12/86 NR GRD PATROL	VICTOR	06/23/2016	09/21/2016	06/28/2016	42731000	Closed	No
104432640	LC	E	E - Schd Compl Yr 0	CAMANCHE TAP 00/008 REMOVE AUTO SPLICE F	VICTOR	01/07/2010	07/31/2014	06/29/2015	42409953	Closed	Yes
105966649	LC	E	E - Schd Compl Yr 0	KASSON-CARBONA 0/4 TRIM VINES	VICTOR	01/13/2015	01/13/2016	01/13/2015	42319492	Closed	No
111624635	LC	E	E - Schd Compl Yr 0	KYOHOTAP 0/4 ACCESS ISSUES	VICTOR	5/5/2016	5/5/2017		42734477	Open	No
111474335	LC	F	F - Schd Compl Yr 1+	LOCKEFORD #1 6/99 RPLC GUY STUB	VICTOR	3/23/2016	3/23/2018		31227563	Open	No
110480769	LC	E	E - Schd Compl Yr 0	LOCKEFORD #1 0/1 GROUND MOLDING	VICTOR	06/23/2015	06/23/2016	09/22/2015	42417720	Closed	No
111821903	LC	E	E - Schd Compl Yr 0	LOCKEFORD #1 4/64 HV	VICTOR	07/11/2016	07/11/2017	09/12/2016	42753555	Closed	No
111822202	LC	E	E - Schd Compl Yr 0	LOCKEFORD #1 8/150 ANCHOR	VICTOR	7/19/2016	7/19/2017		42753586	Open	No
11047422	LC	E	E - Schd Compl Yr 0	LOCKEFORD INDUSTRIAL 0/12 BRIDGE BOND	VICTOR	06/24/2015	06/24/2016	07/15/2015	42417490	Closed	No
11128655	LC	E	E - Schd Compl Yr 0	LOCKEFORD INDUSTRIAL 3/0 HV SIGN	VICTOR	12/23/2015	12/23/2016	02/04/2016	42598224	Closed	No
106888338	CD	A	A - Immed/Safety	LOCKEFORD INDUSTRIAL 000/004 REPLIC POLE	VICTOR	04/24/2013	04/30/2013	05/31/2016	310992927	Closed	Yes
108864054	LC	E	E - Schd Compl Yr 0	TESLA TRACY 007/039 BIRD DIRT CLEAN	VICTOR	08/08/2014	08/08/2015	07/13/2015	42170137	Closed	No
111521524	LC	E	E - Schd Compl Yr 0	TESLA-TRACY 2016 IR PATROL - SR	VICTOR	06/24/2015	06/24/2016	06/17/2016	42659345	Closed	No
111571213	LC	E	E - Schd Compl Yr 0	TESLA-TRACY 18/125 MYLAR BALLOON	VICTOR	04/24/2016	07/23/2016	05/03/2016	426584823	Closed	No
110544135	LC	E	E - Schd Compl Yr 0	TESLA-TRACY 20/136 VEG	VICTOR	07/29/2015	07/29/2016	06/24/2016		Closed	No
110544132	LC	E	E - Schd Compl Yr 0	TESLA-TRACY 21/141 VEG	VICTOR	07/29/2015	07/29/2016	05/23/2016		Closed	No
111418017	LC	E	E - Schd Compl Yr 0	TESLA-TRACY 23/153 STEEL	VICTOR	03/03/2016	03/03/2017	05/16/2016	42648812	Closed	No
111446988	LC	E	E - Schd Compl Yr 0	TESLA-TRACY 31/205 BURIED FOOTING	VICTOR	03/15/2016	03/15/2017	05/09/2016	42692500	Closed	No
111810715	LC	E	E - Schd Compl Yr 0	TESLA-TRACY 31/207 INSTALL ANTI-CLIMB	VICTOR	7/20/2016	7/20/2017		312559661	Open	No
111624744	LC	B	B - Urgt Compliance	TESLA-TRACY 32/210 MEASURED HEIGHT	VICTOR	05/05/2016	08/03/2016	05/05/2016	426598736	Closed	No
111476838	LC	E	E - Schd Compl Yr 0	TESLA-TRACY 33/220 BENT STEEL LEG	VICTOR	03/25/2016	03/25/2017	04/20/2016	426570320	Closed	No
111624771	LC	B	B - Urgt Compliance	WEBER-TELA CONDUCTOR HEIGHT	VICTOR	05/05/2016	08/03/2016	05/05/2016	426598738	Closed	No
111739210	LC	E	E - Schd Compl Yr 0	WEBER-TELA 14/101 REMOVE DEBRIS	VICTOR	06/22/2016	06/22/2017	06/23/2016	42730102	Closed	No
111737836	LC	E	E - Schd Compl Yr 0	WEBER-TELA 19/131 ANTI CLIMBING	VICTOR	06/07/2016	06/07/2017	06/23/2016	311249143	Closed	No
111737559	LC	E	E - Schd Compl Yr 0	WEBER-TELA 25/169 REMOVE TREES	VICTOR	6/2/2016	6/2/2017			Open	No
111807493	LC	E	E - Schd Compl Yr 0	WEBER-TELA 31/208 REMOVE BIRD NEST	VICTOR	07/20/2016	07/20/2017	07/20/2016	42744938	Closed	No
111700432	LC	E	E - Schd Compl Yr 0	WEBER-TELA 35/237 REMOVE FENCE	VICTOR	5/26/2016	5/26/2017			Open	No
111738517	LC	E	E - Schd Compl Yr 0	WEBER-TELA 37/248 FOUNDATION CRACKED	VICTOR	5/26/2016	5/26/2017			Open	No